



Canada

## NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR <b>04-09-2024</b>	REPORT TIME <b>18:00</b>	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR <b>04-09-2024</b>	OCCURRENCE TIME <b>10:45</b>			
C	LAND USE PERMIT NUMBER (IF APPLICABLE)	WATER LICENCE NUMBER (IF APPLICABLE) <b>2AM-WTP-1830</b>			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION <b>WHALE TAIL MINE</b>	REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN			
E	LATITUDE DEGREES <b>65</b> MINUTES <b>01</b> SECONDS <b>51</b>	LONGITUDE DEGREES <b>96</b> MINUTES <b>09</b> SECONDS <b>21</b>			
F	RESPONSIBLE PARTY OR VESSEL NAME <b>AGNICO EAGLE MINES LTD</b>	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION <b>BAKER LAKE X0C 0A0 PO.540</b>			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED <b>TRANSMISSION OIL</b>	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <b>220L</b>	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE <b>TOTE</b>	SPILL CAUSE <b>PUNCTURED TOTE</b>	AREA OF CONTAMINATION IN SQUARE METRES <b>8m2</b>		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS <b>During the operations at the Whale Tail Mine, an operator attempted to extract a tote from the rear of a sea can using a telehandler. Due to a misjudged maneuver, the tote was pierced by the fork, resulting in the release of approximately 220 liters of transmission fluid onto the ground of the Whale Tail warehouse pad. Spill pads were placed on the ground and a loader was used to scrape and remove the contaminated material. The contaminated material was collected and disposed at the proper facility.</b>  <b>Spill Location: 65°24'29" 96°43'12.7" on IOL</b> <b>There were no off-site impacts or discharges. Distance to the closest water body is 575 m to Whale Tail South Lake</b> <b>Contact information: Samuel Tapp 819-759-3555 EXT.: 460-6744</b>				
L	REPORTED TO SPILL LINE BY <b>Samuel Tapp</b>	POSITION <b>Env. Coordinator</b>	EMPLOYER <b>Agnico Eagle Mines</b>	LOCATION CALLING FROM <b>Meadowbank</b>	TELEPHONE <b>819-759-3555</b>
M	ANY ALTERNATE CONTACT <b>Robin Allard</b>	POSITION <b>Env. Gen. Supervisor</b>	EMPLOYER <b>Agnico Eagle Mines</b>	ALTERNATE CONTACT LOCATION <b>Meadowbank</b>	ALTERNATE TELEPHONE <b>819-860-1414</b>
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					