



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 07-12-2024	REPORT TIME 15:50	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 07-12-2024	OCCURRENCE TIME 7:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE)	WATER LICENCE NUMBER (IF APPLICABLE) 2AM-WTP-1830			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION WHALE TAIL MINE	REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN			
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 51	LONGITUDE DEGREES 96 MINUTES 09 SECONDS 21			
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0C 0A0 PO.540			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED ANTI-WASHOUT ADMIXTURE	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 150L	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE TOTE	SPILL CAUSE TBD	AREA OF CONTAMINATION IN SQUARE METRES 20m2		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS During the operations at the Whale Tail Mine, an unidentified substance was observed leaking from a sea can container on the warehouse pad. Upon further investigation, it was determined that the liquid originated from a sea can containing totes of MMATRIX-UW-450, an anti-washout admixture. The nearby sea cans were relocated to allow a loader to scrape and remove the contaminated material. The contaminated material was collected and will be disposed of at the Meadowbank Tailings Storage Facility. Spill Location: 65°23'58.5" 96°40'44.22" on IOL There were no off-site impacts or discharges. Distance to the closest water body is 230 m to Whale Tail South Lake Contact information: Samuel Tapp 819-759-3555 EXT.: 460-6744				
L	REPORTED TO SPILL LINE BY Samuel Tapp	POSITION Env. Coordinator	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM Meadowbank	TELEPHONE 819-759-3555
M	ANY ALTERNATE CONTACT Eric Haley	POSITION Superintendent	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT LOCATION Meadowbank	ALTERNATE TELEPHONE 819-651-1010
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					