NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE
Tel: (867) 920-8130 ● Email: spills@gov.nt.ca

A	Report Date: MM 1 DD 3 25	Report Time: 8:00 am	☑ Original Spill Report **OR** ☐ Update # _____ to the Original Spill Report	**Report Number:**
B	Occurrence Date: MM 1 DD 2 25	Occurrence Time: 11:00 am		
C	Land Use Permit Number (if applicable):		Water Licence Number (if applicable): 2AM-WTP-1830	
D	Geographic Place Name or Distance and Direction from the Named Location: WHALE TAIL MINE		Region: ☐ NT ☑ Nunavut ☐ Trans-boundary or Ocean	
E	Latitude: 65 Degrees 1 Minutes 51 Seconds		Longitude: 96 Degrees 9 Minutes 21 Seconds	
F	Responsible Party or Vessel Name: AGNICO EAGLE MINES LTD		Responsible Party Address or Office Location: BAKER LAKE X0C 0A0 PO.540	
G	Any Contractor Involved:		Contractor Address or Office Location:	
H	Product Spilled: ☐ Potential Spill Coolant	Quantity in Litres, Kilograms or Cubic Metres: 10L	U.N. Number:	
I	Spill Source: Long Haul Truck	Spill Cause: Equipment Failure	Area of Contamination in Square Metres: 2m2	
J	Factors Affecting Spill or Recovery:	Describe Any Assistance Required:	Hazards to Persons, Property or Environment:	

K Summary of the spill incident and efforts / description of the incident:

This spill is reported as due diligence and without prejudice by Agnico Eagle Mines Ltd.

During the operation along the Whale Tail Haul Road a coolant line failed on a long haul truck, resulting in a spill of ~10L of coolant on the road at ~KM178. The contaminated material will be collected and brought to the Meadowbank Tailing Storage Facility.

The spill was within the footprint of the Whale Tail Haul Road. There were no off site impacts or discharges. Distance to the closest water body is ~240m to Lake A57.
Spill Location: 65°24'16.14"N 96°38'1.73"W on IOL

Contact information: Rowan Woodall 819-759-3555 EXT.: 4606744

L	Reported to Spill Line by: Rowan Woodall	Position: Env. Supervisor	Employer: Agnico Eagle Mines	Location Calling From: Meadowbank Complex	Telephone: (819) 759-3555
M	Any Alternate Contact: Robin Allard	Position: Env. Gen. Supervisor	Employer: Agnico Eagle Mines	Alternate Contact Location: Meadowbank Complex	Alternate Telephone: (819) 860-1414

REPORT LINE USE ONLY

N	Received at Spill Line by:	Position:	Employer:	Location Called:	Report Line Number:

Lead Agency: ☐ EC ☐ CCG/TCMSS ☐ GNWT ☐ GN ☐ ILA ☐ CIRNAC ☐ CER ☐ Other: _____

File Status: ☐ Open ☐ Closed

Agency:	Contact Name:	Contact Time:	Remarks:
Lead Agency:			
First Support Agency:			
Second Support Agency:			
Third Support Agency:			