NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE
Tel: (867) 920-8130 ● Email: spills@gov.nt.ca

A	Report Date: MM 11 25	Report Time: 1:15 pm	☑ Original Spill Report OR ☐ Update # _____ to the Original Spill Report	**Report Number:**
B	Occurrence Date: MM 10 25	Occurrence Time: 2:30 pm		
C	Land Use Permit Number (if applicable):		Water Licence Number (if applicable): 2AM-WTP-1830	
D	Geographic Place Name or Distance and Direction from the Named Location: WHALE TAIL MINE		Region: ☐ NT ☑ Nunavut ☐ Trans-boundary or Ocean	
E	Latitude: 65 Degrees 1 Minutes 51 Seconds		Longitude: 96 Degrees 9 Minutes 21 Seconds	
F	Responsible Party or Vessel Name: AGNICO EAGLE MINES LTD		Responsible Party Address or Office Location: BAKER LAKE X0C 0A0 PO.540	
G	Any Contractor Involved:		Contractor Address or Office Location:	
H	Product Spilled: ☐ Potential Spill Hydraulic Oil	Quantity in Litres, Kilograms or Cubic Metres: 2L	U.N. Number:	
I	Spill Source: Excavator	Spill Cause: Mechanical Failure	Area of Contamination in Square Metres: <1m2	
J	Factors Affecting Spill or Recovery:	Describe Any Assistance Required:	Hazards to Persons, Property or Environment:	
K	Summary of the spill incident and efforts / description of the incident: This spill is reported as due diligence and without prejudice by Agnico Eagle Mines Ltd. During an inspection at Whale Tail, operator observed a small hydraulic leak under the parked excavator. The equipment was shut down to stop the leak. The contaminated material will be collected and brought to the Whale Tail Landfarm. The spill was located within the operations footprint. There were no off site impacts or discharges. Distance to the closest water body is 250m to Whale Tail South Lake. Spill Location: 65°23'57.24"N 96°40'38.54"W Contact Information: Tom Thomson 819 759 3555			

L	Reported to Spill Line by: Tom Thomson	Position: Env. Coordinator	Employer: Agnico Eagle Mines Ltd.	Location Calling From: Meadowbank Complex	Telephone: (819) 759-3555
M	Any Alternate Contact: Robin Allard	Position: Env. Gen. Supervisor	Employer: Agnico Eagle Mines Ltd.	Alternate Contact Location: Meadowbank Complex	Alternate Telephone: (819) 860-1414

REPORT LINE USE ONLY

N	Received at Spill Line by:	Position:	Employer:	Location Called:	Report Line Number:

Lead Agency: ☐ EC ☐ CCG/TCMSS ☐ GNWT ☐ GN ☐ ILA ☐ CIRNAC ☐ CER ☐ Other: _____

File Status: ☐ Open ☐ Closed

Agency:	**Contact Name:**	**Contact Time:**	**Remarks:**
Lead Agency:			
First Support Agency:			
Second Support Agency:			
Third Support Agency:			