



## 2025-01-28 WTM 10L Sewage

GN reference #: 2025-088

Please find the following information as a follow up to the Spill report submitted January 29<sup>th</sup>, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

### Spill Description

During operations at Whale Tail Mine, a lift station pump became plugged with foreign material (baby wipes). As a result, the lift station containment overflowed into the building and approximately 10L of sewage spilled onto the ground.



Spill Location: 65°01'.51"N 96°09'21"W (on IOL)

The spill remained within the mine footprint. There were no off-site impacts or discharges. Distance to the closest water body is ≈360m to lake A-56.

### Cause of Spill

Human Error – Non-Flushable wipes were improperly disposed of into the septic system.

## Remediation Actions

The foreign objects were removed from the septic system. Lids for lift stations to be secured down after inspections. The contaminated snow and material was collected and placed in a roll off for disposal at the Meadowbank Tailings Storage Facility.




## Corrective measures

General site reminder to all camp residents of proper hygiene product disposal.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Whale Tail site on January 28<sup>th</sup>, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



**Tom Thomson** | Environmental Coordinator

tom.thomson@agnicoeagle.com | Direct 819.759.3555 | 4606744

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)     

