



AGNICO EAGLE

2025-11-05 WTM Coolant Diesel Hydraulic Oil

GN reference #: 2025-431

Please find the following information as a follow up to the Spill report submitted November 6th, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector as requested; as due diligence and without prejudice by Agnico Eagle Mines Ltd. and in accordance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

Spill Description

While heading southbound on Whale Tail Haul Road, a long-haul truck left the road at kilometer 177. A Code 1 was immediately initiated, and the emergency response team was deployed. The Environment team also attended to assess the situation. Multiple leaks were observed originating from the diesel fuel reservoir, hydraulic system, and cooling system.



Spill Location: 65°24'1.11"N 96° 37'12.21"W

The spill was located along the Whale Tail Haul Road. There were no off-site impacts or discharges. Distance to the closest water body is 270m to an unknown Lake.

Cause of Spill

Human Error. Operator failed to stop when visibility degraded.

Remediation Actions

A secondary containment was placed under the active leak. After further investigation a total of approximately 350L Diesel, 5L of Hydraulic Oil, and 10L of Coolant spilled from the long haul. Contaminated materials were removed and brought to tailing storage facility at the Meadowbank Complex.



Corrective measures

A health and safety investigation was initiated to identify the root cause of the incident and establish appropriate corrective actions. One corrective measure implemented was the addition of color markers on rebars to clearly delineate the designated area. Furthermore, the incident was reviewed with all drivers to reinforce awareness and prevent recurrence.

Closure

We trust that the above details described appropriately the spill incident that occurred on the Whale Tail Haul Road on November 5th, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



Samuel Tapp | Environment Supervisor

samuel.tapp@agnicoeagle.com | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

agnicoeagle.com     

Sent from Amaruq