

INTERNAL	
PC	chp
MA	
FO	
LA	Central
ES	
ST	
TA1	
TA2	
RC	
ED	
GH	
BRD	
BXT	

INDUSTRIAL WATER USE INSPECTION REPORT

DATE: July 15/04 COMPANY REP.: Jim Helyar
LICENSEE: Buster Camp MIRAMAR HOPE BAY LICENCE #: NWBZ HoA 0207
NWB/BOS0106

WATER SUPPLY

Source: Spider Lake Quantity Used: 1232 → 12483 m³ / 15 days Meter Rdg.: 12493

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable
Intake Facilities A Storage Structures A Treatment Systems A Recycling NA
Flow Meas. Device A Conveyance Lines A Pumping Stations A Modifications NA

Comments: Recently there was a hit for fecal coliforms in the weekly analysis of potable water. The UV lamp has been replaced, tank flushed and shock chlorinated with a chlorine residual 0.2 mg/L. Latest sample results came back clean.

WASTE DISPOSAL

Tailings: Tailings Pond Natural Lake Underground
Sewage: Sewage Treat. System Continuos Discharge Tailings Pond Inter. Dischg. Natural Water Body
Solid Waste: shipped out Open Dump Landfill Burn & Bury Underground

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable
Discharge Quality A Conveyance Lines A Disch. Meas. Dev. NA Freeboard NA
Decant Structures NA Pond Treatment NA Dams, Dykes NA Seepages A
Dyke Inspections NA Runoff Diversion NA Erosion NA Spills A

Effluent Discharge Rate: Samples Collected: SNA 1652-5 and Spider Lake on shore at intake
Comments: Samples were taken at Spider Lake at RBC discharge. Sewage treatment appears to be quite effective. Liner on soil farm appears to be in good condition. Large buildup of contaminated soil in drains on site. Metal waste balled up & sent out on Hecla to YK.

GENERAL CONDITIONS

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable
Ore & Waste Rock Stockpiles A Records & Reporting A Surv. Net. Prog. NI
Geotechnical Inspection NA Posting, Signage A Contingency Plan NI
Restoration Activities NA New Construction NA Fuel Storage A
Mine Water Discharge NA Chemical Storage NA Annual Report AINT

Comments: Fuel storage area is well bermed with fuel transfer drums contained in a lined basin. A lined pond is used to contain contaminated water from tank farms & spill site (2000). The water is tested before being pumped onto land.

Violations of Act or Licence: No violations of the Act or Water Licence were observed. No environmental breaches on site so SNA program was not examined. SNA 1652-5 had signage.

General Comments: Some waste oil is immiscible & sent out south. The addition of containment berms around soil transfer points have been a positive addition. Waste oil should be placed on pallets until it can be shipped off site.

Page 2 attached Yes No

Jim Helyar
Licensee Representative's Title
Licensee Representative's Signature

Scott Stewart
Inspector's Name
Inspector's Signature
Nunavut Water Board
NOV 26 2004
Public Registry