



95 Wellington Street W
Suite 1010
P.O. Box 44
Toronto, Ontario
M5J 2N7
416-628-0216

March 29, 2018

Derek Donald
Nunavut Water Board
P.O. Box 119
Gjoa Haven, NU, X0B 1J0

Re: TMAC Response to Boston Advanced Exploration Project 2017 Annual Geotechnical Inspection Letter Recommendations

Dear Derek,

TMAC Resources Inc.'s (TMAC) is pleased to present to the Nunavut Water Board the Boston Advanced Exploration Project 2017 Annual Geotechnical Inspection Letter. This report is required in fulfillment of Part D Item 13 of the Type B Water Licence 2BB-BOS1727. TMAC is providing responses to recommendations made in the report found in Table 1 below.

The Boston Advanced Exploration Project 2017 Annual Geotechnical Inspection report has been submitted to the NWB via email on March 28, 2018 and a hardcopy has been sent to you separately.

Should you have any questions or concerns regarding this submission, please contact me at Oliver.Curran@tmacresources.com.

Sincerely,

Oliver Curran

Vice President, Environmental Affairs
TMAC Resources Inc.

Table 1 TMAC response to Boston Advanced Exploration Project 2017 Annual Geotechnical Inspection Recommendations

| Boston Project 2017 Geotechnical Inspection | | |
|---|---|--|
| Observation | Recommendation | TMAC Response |
| The liner installed in the old sump, previously used for discharge of water collected in the fuel storage area for testing prior to discharge has deteriorated further and slipped. | The sump should not be used without first completing repairs. | TMAC removed this sump from service and a new containment pond sump was constructed in 2017. |