



Vegetation die-back along the western edge of the airstrip south of the Drill Road



Drill Cuttings Settling Pond – looking southwest from the Airstrip



The Boardwalk was removed in 2012 – looking south from the south end of the Airstrip



The Road to Airstrip – looking north over Boston Camp



Ponded water along the western edge of the Airstrip from historic drilling



Impounded water along the edge of the airstrip and the Core Storage Road – looking south




Core boxes north of the Primary Tank Farm



Core boxes stored at the south end of the Camp Complex Foundation Pad



Core boxes in the staging area at the end of the Drill Road.



Only the barrel tests remain at the core storage area by the Core Storage Road



Only minor vegetation damage remains where the V-notch Weir was installed



Only a radio tower remains at the old core box storage area southeast of the Airstrip

| | | |
|---|------------------------------|---|
| | 2014 Geotechnical Inspection | |
| | Core Storage Areas | |
| Job No: 1CT022.000 Filename: Boston Geotech_Figures2014.pptx | HOPE BAY PROJECT | Date: Dec 2014 Approved: LW Figure: 23 |



Grey Water Discharge Location – looking northwest



The west side of the New STP with the foundations for an additional four (4) SaniBrane units – looking south



The original location and rockfill foundation for the new STP – looking northwest from the old STP



The north end of the Old STP – looking south from the Road to Dock