

Hope Bay Mining Ltd.
Suite 300
889 Harbourside Drive
North Vancouver, BC
V7P 3S1
T 604.998.5400
F 604.980.0731
www.newmont.com

February 7, 2013

Phyllis Beaulieu, Manager of Licensing Nunavut Water Board P.O. Box 119 Gjoa Haven, NU X0B 1J0

Re: January 2013 - Monthly Monitoring Report for Water License 2BB-BOS1217

Boston Camp was shut down in November 2011 and was not re-opened in 2012.

Winter site inspections are being conducted monthly while Doris Camp is seasonally closed and the ice between the mainland and Victoria Island allows snowmobile transit. The monthly inspection results are summarized at the end of this report. The full inspection is also attached to this report to comply with AANDC's request to see them.

1. Part D Items 8 and 21 (also Part J Items 2 and 5): Containment Pond, Bulk Fuel Containment, and Land farm

Water was not discharged from BOS-6 (land farm), BOS-5 (bulk fuel containment) or BOS-2 (containment pond).

2. Part J Item 3 and 4: Sewage Treatment Plant Effluent

No samples were taken from monitoring station BOS-3 or BOS-4 as the Sewage Disposal Facility was not operational.

3. Part J: Item 5 and 6: Seepage monitoring

There was no seepage observed in this month.

4. Part J: Item 8 (Reference to Part F: Item 7): Under-Ice Drilling Sampling

Under-ice water quality samples were not collected.

5. Part J Item 11: Water Use Volumes

No water was used as the camp is temporarily closed.

6. Part J Item 12: Mine Water Discharge Volumes

Mine water was not pumped from underground during this period.

7. Part J Items 13 and 14: Sewage Treatment Effluent and Sewage Sludge

Effluent was not discharged at BOS-3 and no sludge was removed from the Sewage Disposal Facility.

Incident Reporting

There were no incidents reported during the month pertaining to this licence.

Winter Site Inspection

The Boston Site and was inspected on January 11, 2013.

No issues of concern were identified during the inspection. The full inspection report, with accompanying photos, is attached.

Should there be any questions regarding this monthly report, please contact Katsky Venter, ESR Site Manager for Hope Bay Mining Limited at (604) 358-7325 or <u>Katsky.Venter@Newmont.com.</u>

Yours sincerely,

Katsky Venter

Environmental and Social Responsibility Site Manager Hope Bay Mining Limited

2012-2013 Hope Bay Boston Care & Maintenance Inspection			NEWN	ORTH AME	RICA	
Inspected By: 1 Tommy Expakorate (Please Print) 2 DENNIS KROMAY & K.	Date of In: (dd/mr		1	1		
Area: Main Camp Perimeter						
1) Signs of entry (forced or wildlife)	Yes	No			monde.	
2) Signs of damage to exterior	Yes	No				
Area: Warehouse and Workshop				A STATE OF THE PARTY OF THE PAR		
1) Signs of entry (forced or wildlife)	Yes	No				
2) Signs of damage to exterior	Yes	No			-	
Area: Boston Fuel Tank Farm						
1) Signs of damage to tank walls / valves	Yes	No			ļ	
2) Signs of leaks or spills	Yes	No				
Inspection Review & Summary (Please report any findings or concerns)						
A						
Findings or concerns (provide photos): OLD WLDLIFE TRACKS AROUND THE						
Camp						
Area:						
Findings or concerns (provide photos):						
General notes on snow conditions (may provide photos):						
Inspector #1 Jamus Epakolial	Inspec	tor #3				
Signatures Inspector #2	Inspec	tor #4				
Primary Contact or designate: ALEX BUCHW Date Reviewed: 01-14-13						



01 11 2013	01 19 301.0
Fuel Tank @ Boston Camp	Fuel Tank @ Boston Camp
01 11 2018	
Boston Camp Facilities	