



February 22, 2011

Via email and Xpresspost

Mr. Richard Dwyer
Licensing Administrator
Nunavut Water Board
PO Box 119
Gjoa Haven, NU X0B 1J0
Phone: (867) 360-6338

Dear Mr. Dwyer,

Re: Water License 2BE-MEA0813 2010 Annual Report

Please find enclosed the 2010 Annual Report as required by Water License 2BE-MEA0813 Part B, Item 2.

Should you require any additional information, please contact me via email at david.frenette@agnico-eagle.com.

Regards,

David Frenette

Encl (1)

NWB Annual Report

Year being reported: 2010 ▼

License No: 2BE-MEA0813 Issued Date: Februray 13, 2008
 Expiry Date: February 28, 2013

Project Name: Meadowbank Exploration Project

Licensee: Agnico-Eagle Mines Limited - Exploration Canada Division

Mailing Address: C.P. 87, 765 Chemin de la Mine Goldex
 Val-d'Or, Quebec J9P 4N9

Name of Company filing Annual Report (If different from Name of Licensee please clarify relationship between the two entitles, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Third Portage Lake for domestic use; water sources proximal to drilling targets	
Water Quantity:	19 cu.m/day	Quantity Allowable Domestic (cu.m)
	6 cu.m/day	Actual Quantity Used Domestic (cu.m)
	250 cu.m/day	Quantity Allowable Drilling (cu.m)
	see below	Total Quantity Used Drilling (cu.m)

Domestic Water Use

The fresh water intake at the Exploration Camp was operational and water intake was metered. The average daily intake for domestic purposes was 6 cu.m/day.

Water Used for Drilling Purposes

Based on the manufacturer's specifications for the water supply pumps used for the diamond drills on the Meadowbank Project, there is 1 cu.m of water pumped per hour equivalent to a maximum possible intake of 19 cu.m per day for each diamond drill.

Three drills were operational during the 2010 exploration program.

The 2010 drilling exploration program had a duration of 135 days with a minimum of 19 cu.m/day for one drill rig and a maximum of 57 cu.m/day if all three rigs were in operation.

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
☒ Sewage
☒ Drill Waste
☒ Greywater
☐ Hazardous
☐ Other:

Additional Details:

Solid Waste:

All solid wastes are sorted at the work sites and regularly transported to the Meadowbank mine site for proper disposal.

Greywater:

There is a "greywater" system installed at the exploration camp. This system includes a grease trap which separates the grease which is collected and transported by vacuum/septic truck to the Meadowbank mine site for disposal on a weekly basis. This system ensures that only "greywater" is released to the environment at the exploration camp site.

Sewage:

All sewage was directed to the sewage holding tank and then transported to the Meadowbank mine site via vacuum/septic truck for processing at the onsite sewage treatment plant.

Drill Waste

Cuttings: When drilling on ice, drill cuttings are accumulated by decantation and collected by vacuum tanker for transport and proper disposition, either at the Meadowbank tailings ponds (when close) or dumped within a natural topographic depression located at least 30 meters away from any water body. A flocculent (Polydrill PD1300) can be used to precipitate the sludge.

Water: Drill water was returned to the lake after cuttings were removed or was pumped to a natural depression sump.

A summary of drilling / trenching operations

Drilling commenced in April and finished in August 2010 with 18860 m drilled over 120 drill holes.

A summary of construction activities

No construction in 2010.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

There were no reported spills in 2010.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates of each location where sources of water are utilized;

Details attached

Additional Details:

The GPS Co-ordinates of each location where wastes associated with the licence are deposited;

Details attached

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

In May and June 2010, AEM collected and analysed water samples for Total Suspended Solids to monitor water quality near the on-ice winter drill sites. Sample locations and laboratory certificates are included in Appendix 1.

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

No other details requested by the Board

Any responses or follow-up actions on inspection/compliance reports

Inspection Report received by the Licensee (Date):

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

09-Feb-11

Submitted/Prepared by:

David Frenette

Contact Information:

Tel: 819-874-5980 ext.3622

Fax: 819-874-3318

email: david.frenette@agnico-eagle.com

Coordinates for domestic water sources

Source Description	Latitude			Longitude		
	Deg °	Min '	Sec "	Deg °	Min '	Sec "
Exploration Camp Fresh Water Intake, Third Portage Lake	65	1	52.7	96	9	9.5

Coordinates for drilling water sources (UTM 83 Z, 14-15)

Source	Easting	Northing
Proximity of drilling site	359109	7218279
Proximity of drilling site	359131	7218552
Proximity of drilling site	359193	7220703
Proximity of drilling site	359539	7218385
Proximity of drilling site	359746	7218557
Proximity of drilling site	360275	7219940
Proximity of drilling site	360279	7220974
Proximity of drilling site	360279	7220974
Proximity of drilling site	361615	7220143
Proximity of drilling site	361615	7220143
Proximity of drilling site	361928	7223065
Proximity of drilling site	363038	7219393
Proximity of drilling site	363038	7219393
Proximity of drilling site	363992	7226239
Proximity of drilling site	364148	7225703
Proximity of drilling site	364421	7227243
Proximity of drilling site	388360	7167190
Proximity of drilling site	388360	7167190
Proximity of drilling site	388437	7167230
Proximity of drilling site	388437	7167230
Proximity of drilling site	402823	7217159
Proximity of drilling site	402823	7217159
Proximity of drilling site	402991	7216672
Proximity of drilling site	403512	7216822
Proximity of drilling site	403512	7216822
Proximity of drilling site	403512	7216822
Proximity of drilling site	404021	7216644
Proximity of drilling site	404243	7217155
Proximity of drilling site	404243	7217155
Proximity of drilling site	627046	7221600
Proximity of drilling site	627726	7224192
Proximity of drilling site	628051	7224344
Proximity of drilling site	628432	7224248
Proximity of drilling site	630066	7194805
Proximity of drilling site	630227	7227973
Proximity of drilling site	630721	7195278
Proximity of drilling site	632971	7229163
Proximity of drilling site	633112	7229058
Proximity of drilling site	633659	7229482
Proximity of drilling site	634347	7201589
Proximity of drilling site	634448	7201180
Proximity of drilling site	634448	7201180
Proximity of drilling site	634623	7226188
Proximity of drilling site	634673	7225830
Proximity of drilling site	635363	7215215
Proximity of drilling site	635370	7214315
Proximity of drilling site	635545	7200748
Proximity of drilling site	635557	7214747
Proximity of drilling site	635583	7201091
Proximity of drilling site	635588	7214401
Proximity of drilling site	636576	7210083
Proximity of drilling site	636738	7228382
Proximity of drilling site	636800	7228394
Proximity of drilling site	636800	7228394
Proximity of drilling site	636804	7228348
Proximity of drilling site	636804	7228348

Proximity of drilling site	636804	7228348
Proximity of drilling site	638115	7229390
Proximity of drilling site	638115	7229390
Proximity of drilling site	638185	7228220
Proximity of drilling site	638233	7228284
Proximity of drilling site	638233	7228284
Proximity of drilling site	638233	7228284
Proximity of drilling site	638256	7229070
Proximity of drilling site	638496	7217074
Proximity of drilling site	638635	7217099
Proximity of drilling site	638705	7217123
Proximity of drilling site	638822	7215562
Proximity of drilling site	638822	7215562
Proximity of drilling site	638822	7215562
Proximity of drilling site	638822	7215562
Proximity of drilling site	638822	7215562
Proximity of drilling site	638822	7215562
Proximity of drilling site	638822	7215562
Proximity of drilling site	639175	7220867
Proximity of drilling site	639492	7218420
Proximity of drilling site	639586	7217234
Proximity of drilling site	639586	7217234
Proximity of drilling site	639586	7217234
Proximity of drilling site	640095	7218163
Proximity of drilling site	640260	7214979
Proximity of drilling site	640260	7214979
Proximity of drilling site	640675	7214345
Proximity of drilling site	640783	7217939
Proximity of drilling site	640808	7216848
Proximity of drilling site	640859	7217865
Proximity of drilling site	640859	7217865
Proximity of drilling site	640958	7217981
Proximity of drilling site	641004	7215675
Proximity of drilling site	641004	7215675
Proximity of drilling site	641036	7215340
Proximity of drilling site	641039	7217962
Proximity of drilling site	641050	7217044
Proximity of drilling site	641085	7215674
Proximity of drilling site	641085	7215674
Proximity of drilling site	641102	7217940
Proximity of drilling site	641113	7215245
Proximity of drilling site	641147	7216329
Proximity of drilling site	641147	7216329
Proximity of drilling site	641147	7216329


Coordinates for areas of waste deposit

Description	Latitude			Longitude		
	° Deg	' Min	'' Sec	° Deg	' Min	'' Sec
Grey Water Discharge Line	65	1	51.2	96	9	28.3

Coordinates for drilling waste deposit

Description	Easting	Northing
Drill Cuttings Summer-natural sump	360275	7219940
Drill Cuttings Summer-natural sump	633112	7229058
Drill Cuttings Summer-natural sump	632971	7229163
Drill Cuttings Summer-natural sump	633659	7229482
Drill Cuttings Summer-natural sump	641147	7216329
Drill Cuttings Summer-natural sump	641147	7216329
Drill Cuttings Summer-natural sump	641147	7216329
Drill Cuttings Summer-natural sump	641004	7215675


Drill Cuttings Summer-natural sump	641004	7215675
Drill Cuttings Summer-natural sump	640260	7214979
Drill Cuttings Summer-natural sump	640260	7214979
Drill Cuttings Summer-natural sump	630227	7227973
Drill Cuttings Summer-natural sump	363038	7219393
Drill Cuttings Summer-natural sump	363038	7219393
Drill Cuttings Summer-natural sump	388437	7167230
Drill Cuttings Summer-natural sump	388437	7167230
Drill Cuttings Summer-natural sump	388360	7167190
Drill Cuttings Summer-natural sump	388360	7167190
Drill Cuttings Summer-natural sump	636576	7210083
Drill Cuttings Summer-natural sump	627046	7221600
Drill Cuttings Summer-natural sump	364421	7227243
Drill Cuttings Summer-natural sump	363992	7226239
Drill Cuttings Summer-natural sump	364148	7225703
Drill Cuttings Summer-natural sump	402991	7216672
Drill Cuttings Summer-natural sump	403512	7216822
Drill Cuttings Summer-natural sump	403512	7216822
Drill Cuttings Summer-natural sump	403512	7216822
Drill Cuttings Summer-natural sump	404021	7216644
Drill Cuttings Summer-natural sump	404243	7217155
Drill Cuttings Summer-natural sump	404243	7217155
Drill Cuttings Summer-natural sump	402823	7217159
Drill Cuttings Summer-natural sump	402823	7217159
Drill Cuttings Summer-natural sump	361615	7220143
Drill Cuttings Summer-natural sump	361615	7220143
Drill Cuttings Summer-natural sump	636804	7228348
Drill Cuttings Summer-natural sump	636738	7228382
Drill Cuttings Summer-natural sump	636800	7228394
Drill Cuttings Summer-natural sump	636804	7228348
Drill Cuttings Summer-natural sump	636804	7228348
Drill Cuttings Summer-natural sump	638115	7229390
Drill Cuttings Summer-natural sump	638256	7229070
Drill Cuttings Summer-natural sump	638115	7229390
Drill Cuttings Summer-natural sump	638233	7228284
Drill Cuttings Summer-natural sump	638233	7228284
Drill Cuttings Summer-natural sump	638233	7228284
Drill Cuttings Summer-natural sump	638185	7228220
Drill Cuttings Summer-natural sump	634347	7201589
Drill Cuttings Summer-natural sump	635583	7201091
Drill Cuttings Summer-natural sump	634448	7201180
Drill Cuttings Summer-natural sump	634448	7201180
Drill Cuttings Summer-natural sump	635545	7200748
Drill Cuttings Summer-natural sump	630721	7195278
Drill Cuttings Summer-natural sump	630066	7194805
Drill Cuttings Summer-natural sump	638635	7217099
Drill Cuttings Summer-natural sump	640859	7217865
Drill Cuttings Summer-natural sump	640859	7217865
Drill Cuttings Summer-natural sump	641039	7217962
Drill Cuttings Summer-natural sump	638496	7217074
Drill Cuttings Summer-natural sump	638705	7217123
Drill Cuttings Summer-natural sump	639492	7218420
Drill Cuttings Summer-natural sump	640095	7218163
Drill Cuttings Summer-natural sump	359746	7218557
Drill Cuttings Summer-natural sump	359131	7218552
Drill Cuttings Summer-natural sump	359539	7218385
Drill Cuttings Summer-natural sump	359109	7218279
Drill Cuttings Summer-natural sump	641102	7217940
Drill Cuttings Summer-natural sump	640958	7217981
Drill Cuttings Summer-natural sump	640783	7217939




Sample sites 2010

Legend

CrownLeases



ClaimsNTI



ClaimsNAC



Lake



Samples_sites



1:15 000

Map creation: 2011-02-09

Hole number	ORIGEASTIN	ORIGNORTH	GRIDORIG	Site	Date	TSS (mg/L)	Date	TSS	Date	TSS
CK10-010	360563	7221637	UTM83-Z15:	Cricket	30-05-2010	<1				
CK10-012	360346	7221389	UTM83-Z15:	Cricket	01-05-2010	4				
EB10-008	640705	7215650	UTM83-Z14:	East BIF	10-05-2010	11	31-05-2010	1		
FW10-004	635739	7212857	UTM83-Z14:	Far West	29-04-2010	<1	10-05-2010	2	30-05-2010	5
FW10-005	634633	7213935	UTM83-Z14:	Far West	02-05-2010	<1	06-05-2010	1		
FW10-010	634668	7215898	UTM83-Z14:	Far West	10-05-2010	13	31-05-2010	<1		
FW10-012	635412	7215173	UTM83-Z14:	Far West	22-05-2010	2	19-05-2010	2		
FW10-013	635541	7214745	UTM83-Z14:	Far West	23-05-2010	2	22-05-2010	2		
MB10-014	361636	7222786	UTM83-Z15:	Marge Bay	11-04-2010	11				
MB10-019	362371	7224221	UTM83-Z15:	Marge Bay	03-05-2010	6	30-05-2010	<1		
SGL10-001	632196	7228033	UTM83-Z14:	Sightless	29-05-2010	7				
VLT10-324	360135	7220941	UTM83-Z15:	Vault	10-05-2010	<1				
VLT10-325	359764	7220578	UTM83-Z15:	Vault	30-05-2010	1				



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Goldex
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-79963
Sampling date: April 29, 2010
Sampling hour: 08:00
Date received: May 04, 2010
Sampling location: FW-10-004
Sampled by: Denis Goyette
Matrix: Water
Sample name: FW-10-004

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	<1 mg/L	M-SOLI-1.0	May 05, 2010
Turbidity	0.42 NTU	M-TURB-1.0	May 05, 2010

Reported on: May 06, 2010

Jean-François Bouffard

Jean-François Bouffard, Chimiste
2008-026
J'approuve le certificat
2010.05.07 14:35:42 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Goldex
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-79965
Sampling date: May 01, 2010
Sampling hour: 14:00
Date received: May 04, 2010
Sampling location: CK10-012
Sampled by: Denis Goyette
Matrix: Water
Sample name: CK10-012

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	4 mg/L	M-SOLI-1.0	May 05, 2010
Turbidity	1.8 NTU	M-TURB-1.0	May 05, 2010

Reported on: May 06, 2010

Jean-François Bouffard

Jean-François Bouffard, Chimiste
2008-026
J'approuve le certificat
2010.05.07 14:37:31 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Goldex
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-79966
Sampling date: May 02, 2010
Sampling hour: 10:00
Date received: May 04, 2010
Sampling location: FW10-005
Sampled by: Denis Goyette
Matrix: Water
Sample name: FW10-005

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	<1 mg/L	M-SOLI-1.0	May 05, 2010
Turbidity	0.41 NTU	M-TURB-1.0	May 05, 2010

Reported on: May 06, 2010

Jean-François Bouffard

Jean-François Bouffard, Chimiste
2008-026
J'approuve le certificat
2010.05.07 14:38:58 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Goldex
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: **C-79967**
Sampling date: May 03, 2010
Sampling hour: 12:15
Date received: May 04, 2010
Sampling location: MB10-019
Sampled by: Denis Goyette
Matrix: Water
Sample name: MB10-019

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	6 mg/L	M-SOLI-1.0	May 05, 2010
Turbidity	3.7 NTU	M-TURB-1.0	May 05, 2010

Reported on: May 06, 2010

Jean-François Bouffard

Jean-François Bouffard, Chimiste
2008-026
J'approuve le certificat
2010.05.07 14:40:06 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.

125, boul Industriel
Rotin-Noranda (Québec)
J9X 6P2
Tél: (819) 797-0550
Fax: (819) 797-2155
Courriel:
multilab@cablevision.qc.ca



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Goldex
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-79968
Sampling date: April 11, 2010
Sampling hour: N/D
Date received: May 04, 2010
Sampling location: MB10-014
Sampled by: Denis Goyette
Matrix: Water
Sample name: MB10-014

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	11 mg/L	M-SOLI-1.0	May 05, 2010
Turbidity	4.5 NTU	M-TURB-1.0	May 05, 2010

Reported on: May 06, 2010

Jean-François Bouffard

Jean-François Bouffard, Chimiste
2008-026
J'approuve le certificat
2010.05.07 14:41:15 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-80196
Sampling date: May 06, 2010
Sampling hour: N/D
Date received: May 07, 2010
Sampling location: FW10-05
Sampled by: Denis Goyette
Matrix: Water
Sample name: FW10-05

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	1 mg/L	M-SOLI-1.0	May 10, 2010
Turbidity	0.88 NTU	M-TURB-1.0	May 07, 2010

Reported on: May 10, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.05.10 16:00:17 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.

Results summary

Client: Agnico Eagle Division Exploration

Company: M. Denis Vaillancourt

Address: C.P. 87 Chemin de la Mine Goldex

Val d'Or Qc J9P 4N9

Phone: (819) 874-5980 (3605)

Fax: (819) 874-3318

Date received: May 18, 2010

Sampled by: Danid Goyette

Matrix: Water

Lab number:	80670	80671	80672	80673
Sample name:	EB-10-08	VLT-10-324	FW-10-04	FW-10-10
Sampling date:	10-05-2010	10-05-2010	10-05-2010	10-05-2010
Total Suspended Solids mg/L	11	<1	2	13
Turbidity NTU	3.0	0.50	2.0	2.1

Roger Turmel, Chimiste
J'approuve le certificat
2010.05.19 14:22:44 -04'00'



These results are as followed on the Certificate's analysis of the corresponding project number.
In case of difference between these files , the results are signed on the results summary

Reported on: May 19, 2010

F-02-13
Version 2ième: 18/10/2006

Page 1 of 1



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-81007
Sampling date: May 22, 2010
Sampling hour: 08:30
Date received: May 25, 2010
Sampling location: FW-10-12
Sampled by: Martin Boulet
Matrix: Water
Sample name: FW-10-12

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	2 mg/L	M-SOLI-1.0	May 26, 2010
Turbidity	0.38 NTU	M-TURB-1.0	May 25, 2010

Reported on: May 26, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.05.26 11:17:25 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-81008
Sampling date: May 19, 2010
Sampling hour: 10:00
Date received: May 25, 2010
Sampling location: FW-10-12 eau forage
Sampled by: Martin Boulet
Matrix: Water
Sample name: FW-10-12 eau forage

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	2 mg/L	M-SOLI-1.0	May 26, 2010

Reported on: May 26, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.05.26 11:18:18 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.

125, boul Industriel
Rouyn-Noranda (Québec)
J9X 6P2
Tél: (819) 797-0550
Fax: (819) 797-2155
Courriel:
multilab@cablevision.qc.ca



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-81009
Sampling date: May 23, 2010
Sampling hour: 14:30
Date received: May 25, 2010
Sampling location: FW-10-13
Sampled by: Martin Boulet
Matrix: Water
Sample name: FW-10-13

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	2 mg/L	M-SOLI-1.0	May 26, 2010
Turbidity	0.29 NTU	M-TURB-1.0	May 25, 2010

Reported on: May 26, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.05.26 11:19:58 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-81010
Sampling date: May 22, 2010
Sampling hour: 08:45
Date received: May 25, 2010
Sampling location: FW-10-13
Sampled by: Martin Boulet
Matrix: Water
Sample name: FW-10-13

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	2 mg/L	M-SOLI-1.0	May 26, 2010
Turbidity	0.59 NTU	M-TURB-1.0	May 25, 2010

Reported on: May 26, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.05.26 11:21:01 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.

125, boul Industriel
Rouyn-Noranda (Québec)
J9X 6P2
Tél: (819) 797-0550
Fax: (819) 797-2155
Courriel:
multilab@cablevision.qc.ca



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-81427
Sampling date: May 29, 2010
Sampling hour: 14:00
Date received: June 01, 2010
Sampling location: SGL 10-001
Sampled by: Denis Goyette
Matrix: Waste Water
Sample name: SGL 10-001

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	7 mg/L	M-SOLI-1.0	June 03, 2010
Turbidity	1.1 NTU	Sous-traitance\Maxxam	June 02, 2010

Reported on: June 10, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.06.10 13:06:44 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-81428
Sampling date: May 30, 2010
Sampling hour: 13:30
Date received: June 01, 2010
Sampling location: FW--10-04
Sampled by: Denis Goyette
Matrix: Waste Water
Sample name: FW--10-04

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	5 mg/L	M-SOLI-1.0	June 03, 2010
Turbidity	8.7 NTU	Sous-traitance\Maxxam	June 02, 2010

Reported on: June 10, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.06.10 13:14:20 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.



Analytical Report

Company: **Agnico Eagle Division Exploration**

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-81429
Sampling date: May 30, 2010
Sampling hour: 14:30
Date received: June 01, 2010
Sampling location: MB-10-19
Sampled by: Denis Goyette
Matrix: Waste Water
Sample name: MB-10-19

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	<1 mg/L	M-SOLI-1.0	June 03, 2010
Turbidity	0.4 NTU	Sous-traitance\Maxxam	June 02, 2010

Reported on: June 10, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.06.10 13:15:43 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-81430
Sampling date: May 30, 2010
Sampling hour: 15:00
Date received: June 01, 2010
Sampling location: CK-10-10
Sampled by: Denis Goyette
Matrix: Waste Water
Sample name: CK-10-10

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	<1 mg/L	M-SOLI-1.0	June 03, 2010
Turbidity	0.2 NTU	Sous-traitance\Maxxam	June 02, 2010

Reported on: June 10, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.06.10 13:17:04 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.

125, boul Industriel
Rouyn-Noranda (Québec)
J9X 6P2
Tél: (819) 797-0550
Fax: (819) 797-2155
Courriel:
multilab@cablevision.qc.ca



Analytical Report

Company: **Agnico Eagle Division Exploration**

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-81431
Sampling date: May 30, 2010
Sampling hour: 15:30
Date received: June 01, 2010
Sampling location: VLT10-325
Sampled by: Denis Goyette
Matrix: Waste Water
Sample name: VLT10-325

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	1 mg/L	M-SOLI-1.0	June 03, 2010
Turbidity	0.3 NTU	Sous-traitance\Maxxam	June 02, 2010

Reported on: June 10, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.06.10 13:24:54 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.



Analytical Report

Company: Agnico Eagle Division Exploration

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-81432
Sampling date: May 31, 2010
Sampling hour: 09:00
Date received: June 01, 2010
Sampling location: EB-10-08
Sampled by: Denis Goyette
Matrix: Waste Water
Sample name: EB-10-08

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	1 mg/L	M-SOLI-1.0	June 03, 2010
Turbidity	0.1 NTU	Sous-traitance\Maxxam	June 02, 2010

Reported on: June 10, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.06.10 13:25:38 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.



Analytical Report

Company: **Agnico Eagle Division Exploration**

Client: M. Denis Vaillancourt
Address: C.P. 87 Chemin de la Mine Golde
Val d'Or Qc J9P 4N9
Phone: (819) 874-5980 (3605)
Fax: (819) 874-3318

Lab number: C-81433
Sampling date: May 31, 2010
Sampling hour: 09:30
Date received: June 01, 2010
Sampling location: FW-10-10
Sampled by: Denis Goyette
Matrix: Waste Water
Sample name: FW-10-10

Parameter	Result	Method name	Date analyzed
Total Suspended Solids	<1 mg/L	M-SOLI-1.0	June 03, 2010
Turbidity	0.2 NTU	Sous-traitance\Maxxam	June 02, 2010

Reported on: June 10, 2010

Roger Turmel, Chimiste
J'approuve le certificat
2010.06.10 13:26:57 -04'00'

Results relate only to the sample tested.

This report shall not be reproduced except in full without the written authority of the laboratory.

All samples will be disposed of after 30 days following analysis.

125, boul Industriel
Rouyn-Noranda (Québec)
J9X 6P2
Tél: (819) 797-0550
Fax: (819) 797-2155
Courriel:
multilab@cablevision.qc.ca