







Inspection 2016 during freshet, crossing 181

Upstream	Downstream
	
2016-05-10	
	
2016-05-14	
No picture	
	
2016-05-20	

Inspection 2016 during freshet, crossing 181




Upstream	Downstream
	
2016-05-26	
	
2016-05-28	
	
2016-05-31	

Inspection 2016 during freshet, crossing 181

Upstream	Downstream
	
2016-06-01	
	
2016-06-03	
	
2016-06-07	











Inspection 2016 during freshet, crossing 181



Upstream	Downstream
	
2016-06-12	
	
2016-06-13	
	
2016-06-14	
	
2016-06-15	



Inspection 2016 during freshet, crossing 181

Upstream	Downstream
	
2016-06-18	
	
2016-06-28	
	
2016-06-29	
	
2016-07-01	

Inspection 2016 during freshet, crossing 181

Upstream	Downstream
	
2016-07-04	
	
2016-07-18	