



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 06-11-2018	REPORT TIME 14:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 06-11-2018	OCCURRENCE TIME 10:20			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KVCL314C01	WATER LICENCE NUMBER (IF APPLICABLE) 2BB-MEA1318			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Amaruq camp		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 51		LONGITUDE DEGREES 96 MINUTES 09 SECONDS 21		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION 765, chemin de la mine Goldex c.p. 87, Val d'Or, QC, Canada			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED Diesel fuel	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 115 L	U.N. NUMBER U.N. 1202		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE Fill-Rite Fuel Pump	SPILL CAUSE Equipment breakdown	AREA OF CONTAMINATION IN SQUARE METRES		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS A worker was transferring fuel from a 1135 L fuel tank to a 1000 L tote when he noticed that the tote was leaking from the bottom. The fuel transfer was immediately stopped and the fuel was recovered using absorbent sheets and booms. The contaminated ground was scrapped using a backhoe. The soil has been temporarily stored and will be brought to the Meadowbank mine landfarm. There were no offsite impacts or discharge to any receiving watercourses. Spill location: Northing: 65°01'51 Easting: 96°09'21 on IOL Contact Information: Robin Allard 819-759-3555 ext. 6744				
L	REPORTED TO SPILL LINE BY ROBIN ALLARD	POSITION SR COORDINATOR	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM Meadowbank	TELEPHONE 8197593555
M	ANY ALTERNATE CONTACT NANCY D-HARVEY	POSITION SUPERINTENDENT	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT LOCATION Nunavut	ALTERNATE TELEPHONE 8677934610
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					