



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 2019-01-27	REPORT TIME 17:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 2019-01-27	OCCURRENCE TIME 03:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE) NWB-2BB-MEA1318		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION WHALE TAIL PIT PROJECT		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 51		LONGITUDE DEGREES 96 MINUTES 09 SECONDS 21		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED Orbit Garant	CONTRACTOR ADDRESS OR OFFICE LOCATION Val-d'Or J9P 6Y6			
H	PRODUCT SPILLED Engine oil	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 5L	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE Drill SH-61 #1	SPILL CAUSE Mechanical Failure	AREA OF CONTAMINATION IN SQUARE METRES 1 m2		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS While the drill SH-61 #1 was operating on the Whale Tail North lake, the hose feeding the feed cylinder busted causing 30L of engine oil to spill in the secondary containment. Because of the water contained in the secondary containment, 5 liters of the engine oil got in contact with the ice of the lake. The drill operators used absorbent pads to clean-up and disposed of the contaminated material at the appropriated facility. Spill Location: N 65°24'16.1" W 096°41'58.8" Contact Information: Martin Archambault 819-759-3555 ext. 6744				
L	REPORTED TO SPILL LINE BY Martin Archambault	POSITION Sr. Coordinator	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM Amaruq	TELEPHONE 8197593555
M	ANY ALTERNATE CONTACT Robin Allard	POSITION General Supervisor	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT LOCATION Nunavut	ALTERNATE TELEPHONE 8198601414
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					