



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 02-04-2019		REPORT TIME 16:30		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	B	OCCURRENCE DATE: MONTH – DAY – YEAR 02-03-2019		OCCURRENCE TIME 23:00		
C		LAND USE PERMIT NUMBER (IF APPLICABLE)			WATER LICENCE NUMBER (IF APPLICABLE) NWB-2BB-MEA1318	
	D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION WHALE TAIL PIT PROJECT			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E		LATITUDE DEGREES 65 MINUTES 01 SECONDS 51			LONGITUDE DEGREES 96 MINUTES 09 SECONDS 21	
	F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0		
G		ANY CONTRACTOR INVOLVED Orbit Garant		CONTRACTOR ADDRESS OR OFFICE LOCATION Val-d'Or J9P 6Y6		
	H	PRODUCT SPILLED Engine Oil		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 3L		U.N. NUMBER
SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER		
I	SPILL SOURCE Drill SH-64		SPILL CAUSE Mechanical Failure		AREA OF CONTAMINATION IN SQUARE METRES 1 m2	
	FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS					
	<p>While the drill SH-64 was operating on the Whale Tail North lake, the seal gasket from the pump popped causing a spill in the secondary containment inside the drill. Unfortunately, 3 liter of engine oil got in contact with a snow outside the drill.</p>					
	<p>The drill operators shoveled the snow and disposed it at the appropriated facility.</p>					
	<p>Spill Location: N 65°24'25.5" W 096°41'48.9"</p> <p>Contact Information: Martin Archambault 819-759-3555 ext. 6744</p>					
L	REPORTED TO SPILL LINE BY Martin Archambault		POSITION Sr. Coordinator	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM Amaruq	TELEPHONE 8197593555
	ANY ALTERNATE CONTACT Robin Allard		POSITION General Supervisor	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT LOCATION Nunavut	ALTERNATE TELEPHONE 8198601414
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY		POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
	LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						