



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 02-07-2019	REPORT TIME 9:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 02-06-2019	OCCURRENCE TIME 15:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE) NWB-2BB-MEA1318		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION WHALE TAIL PIT PROJECT		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 51		LONGITUDE DEGREES 96 MINUTES 09 SECONDS 21		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED Orbit Garant	CONTRACTOR ADDRESS OR OFFICE LOCATION Val-d'Or J9P 6Y6			
H	PRODUCT SPILLED Engine Oil	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 4L	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE Drill SH-47	SPILL CAUSE Mechanical Failure	AREA OF CONTAMINATION IN SQUARE METRES 1 m2		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS While the drill SH-47 was operating on the Whale Tail North lake, the motor broke down, engine oil leaked from the vent causing a spill in the secondary containment inside the drill but 4 liters of oil has overflowed the containment and goes on snow. All contaminated snow was removed and brought in the appropriate bin. Spill Location: N 65°24'15.62" W 96°41'53.52" Contact Information: Martin Archambault 819-759-3555 ext. 6744				
L	REPORTED TO SPILL LINE BY Martin Archambault	POSITION Sr. Coordinator	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM Amaruq	TELEPHONE 8197593555
M	ANY ALTERNATE CONTACT Robin Allard	POSITION General Supervisor	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT LOCATION Nunavut	ALTERNATE TELEPHONE 8198601414
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					