



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 09-09-2021	REPORT TIME 13:20	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 09-08-2021	OCCURRENCE TIME 15:00		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) N2016C0003	WATER LICENCE NUMBER (IF APPLICABLE) 2BB-MEA1828		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Meadowbank Exploration Project	REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 06 SECONDS 13	LONGITUDE DEGREES 96 MINUTES 17 SECONDS 24		
F	RESPONSIBLE PARTY OR VESSEL NAME Agnico Eagle Mines Ltd.	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Exploration Division, Val-d'Or, Qc		
G	ANY CONTRACTOR INVOLVED Orbit Garant Drilling	CONTRACTOR ADDRESS OR OFFICE LOCATION Val-d'Or, Qc		
H	PRODUCT SPILLED Diesel	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES +100L	U.N. NUMBER 1202	
H	SECOND PRODUCT SPILLED (IF APPLICABLE) N/A	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES N/A	U.N. NUMBER N/A	
I	SPILL SOURCE Diamond Drill	SPILL CAUSE Human Error	AREA OF CONTAMINATION IN SQUARE METRES TBD	
J	FACTORS AFFECTING SPILL OR RECOVERY Distance from the mine site	DESCRIBE ANY ASSISTANCE REQUIRED N/A	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT N/A	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS On September 8 2021, while working on the drill engine, a fuel hose located between the engine and the fuel tank has been unplugged, but has been left on the ground without having stopped the fuel entry resulting with fuel spill on the tundra. The spill was stopped, the diamond drill was moved to be able to clean under. Cleaning is still ongoing.			
L	REPORTED TO SPILL LINE BY David Frenette	POSITION Env. Coord	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM Val-d'Or
M	ANY ALTERNATE CONTACT Gabriel Côté	POSITION Geologist	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT Meadowbank
REPORT LINE USE ONLY				
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN	FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS
LEAD AGENCY				
FIRST SUPPORT AGENCY				
SECOND SUPPORT AGENCY				
THIRD SUPPORT AGENCY				