



Photo 23 May 2003 snow survey. Digging snow pit in deep drift for staged snow tube sampling.




Photo 24 May 2003 snow survey. Probing snow depth on steep SE slope.



Photo 25 May 2003. Coring through lake ice to measure pre-runoff lake water level.



Photo 26 9 June 2003. Second Portage Lake attempting to place sensor orifice block through the ice to start station operation.




Photo 27      23 June 2004. Upstream of Drilltrail Lake outlet channel looking south.




Photo 28      23 June 2004. Downstream of Tern Lake outlet channel looking north.



Photo 29      23 June 2004. Downstream of 3PL west outlet channel looking south.



Photo 30      23 June 2004. Downstream of 2PL outlet control looking northwest.