


## MELIADINE ROAD CROSSING: M2.1

Parameter	Value	Note
Bankfull Width	Approx. 75 m	Measured in the field
Bankfull Depth	Approx. 3.25 m	Measured in the field
Approximate Channel Length	Over 39 km	From NTS Maps
Slope	0.00285 m/m	Measured in the field
Bed Material	50% boulder, 20% cobble, 20% gravel, 10% fines	
Bank Material	Boulders, organics	
Bank Vegetation	Grass	
UTM Coordinates (Easting, Northing)	544835 m, 6971643 m	NAD83 Zone 15
Comment	Erosion was noticed on the right downstream bank. See Fisheries Baseline Studies 2008 (Golder 2008) for additional information.	



10 July 2008. Downstream view of watercourse crossing looking at left downstream bank.



10 July 2008. Downstream view of watercourse crossing.