



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 06-01-2021	REPORT TIME 10:00	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 05-31-2021	OCCURRENCE TIME 15:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KVPL11D01	WATER LICENCE NUMBER (IF APPLICABLE) 2BB-MEL-1424			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Meliadine Gold Project		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 63 MINUTES 1 SECONDS 30		LONGITUDE DEGREES 92 MINUTES 14 SECONDS 39		
F	RESPONSIBLE PARTY OR VESSEL NAME Agnico Eagle Mines Ltd.	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Meliadine, Rankin Inlet, Nunavut, X0C 0G0			
G	ANY CONTRACTOR INVOLVED Orbit Garant	CONTRACTOR ADDRESS OR OFFICE LOCATION Val d'Or, Quebec			
H	PRODUCT SPILLED Hydraulic Oil	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 5 liters	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE Drill Rig	SPILL CAUSE Runoff in contact with drill	AREA OF CONTAMINATION IN SQUARE METRES 50		
J	FACTORS AFFECTING SPILL OR RECOVERY Surface Runoff	DESCRIBE ANY ASSISTANCE REQUIRED N/A	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT None		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS During an exploratory drilling campaign near local lake B5, workers noticed an oil sheen on the surface runoff surrounding the drill. Absorbent pads and booms were set up to capture surface hydrocarbons. Pursuant to Part H, Section 4c of the water licence, a follow-up report will be issued after a closer investigation is completed. Reported by Sean Arruda, Environment Coordinator, 819-759-3555 ext. 4603996 Contact: Robin Allard, Environment General Supervisor 819-860-1414 meli.environment.supervisors@agnicoeagle.com				
L	REPORTED TO SPILL LINE BY Sean Arruda	POSITION Coordinator	EMPLOYER Agnico Eagle	LOCATION CALLING FROM Meliadine	TELEPHONE 819-759-3555
M	ANY ALTERNATE CONTACT Robin Allard	POSITION General Supervisor	EMPLOYER Agnico Eagle	ALTERNATE CONTACT Meliadine LOCATION	ALTERNATE TELEPHONE 819-860-1414
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					