

Meliadine Gold Project NWB 2BB-MEL1424 September 2019 Monthly Report

**Prepared for:** 

Nunavut Water Board

Prepared by:

Agnico Eagle Mines Limited – Meliadine Division

October 30th, 2019

This monthly report is delivered under water license 2BB-MEL1424, PART J, Item 13.

## 1. The Licensee shall maintain Monitoring Stations at the following locations:

Table 1: Monitoring stations

Monitoring Station	Description	Status	
MEL-1	Raw water supply intake at Meliadine Lake	Active (Volume m³)	
MEL-2	Raw water supply intake at Pump, A8 or other Lakes	Active (Volume m³)	
MEL-5	Point of discharge for the Bermed Fuel Containment Facilities	Inactive	
MEL-6	Effluent from the Landfarm Treatment Facility prior to release	Inactive	
MEL-7	Final Effluent Discharge from the BIODISK treatment system	Active (no direct discharge)	
MEL-8	Point of discharge or runoff from the Non-Hazardous Waste landfill	Inactive	

## 2. The Licensee shall measure and record, in cubic metres, the daily quantities of water utilized for camp, drilling and other purposes from all sources.

3.

Table 2: Water quantities utilized (average)

able 2. Water qualitities at	inzed (dverage)		
	Camp	m³/day	3.18
MEL-1 <sup>1</sup>	Pump Shack	m³/day	8.30
	Construction	m³/day	0.00
MEL-2 (A8) <sup>2</sup>	Underground	m³/day	0.00
IVIEL-Z (AO)	Drilling	m³/day	0.00
Not MEL-1 or MEL-2	Drilling	m³/day	72.46
Daily Average		m³/day	83.94
Total September 2019		$m^3$	2,518
Total 2019		m <sup>3</sup>	18,937

## 4. The Licensee shall measure and record the volume of all soil from all locations entering the Landfarm Treatment Facility.

In September 2019, no material was deposited in the Type B landfarm. Any new contaminated soil generated will be deposited in the Landfarm approved in the Type A Water License. Screening of the material in Landfarm B occurred in September.

<sup>&</sup>lt;sup>1</sup> MEL-1: 541943E, 6989174N

<sup>&</sup>lt;sup>2</sup> MEL-2 (A8): 540076E, 6987731N

 The Licensee shall assess and record the concentration of F1 – F4 fractions in petroleum hydrocarbon contaminated soil, according to the CCME Canada-Wide Standard for Petroleum Hydrocarbons (PHC) in Soil that is entering the Land Treatment Unit from all sources and excavations.

Samples were taken from the screened contaminated soil in September.

6. The Licensee shall provide the GPS coordinates (in decimal degrees) of all locations where wastes associated with camp operations and exploration activities are deposited.

No more waste from camp operations and exploration is deposited in locations related to Licence 2BB-MEL1424

7. Licensee shall sample at Monitoring Program Station MEL-7, monthly during wastewater effluent discharge. Samples shall be analyzed for the parameters listed under Part D Item 11:

pH
Biochemical Oxygen Demand – BOD5
Total Suspended Solids (TSS)
Fecal Coliforms
Oil and Grease (and visual)

From Nov, 2017 to April 2019, all treated sewage from the Exploration Camp STP was trucked and deposited in CP1. From April 15th 2019 to early June, due to inconsistency in the amount of people at the exploration camp resulting in unsteady STP effluent results, AEM decided to transfer all treated water from the exploration STP to the main camp STP for a second treatment before being discharge in CP-1. Since early June, the treated sewage from the exploration camp is deposited in CP-1 as sampling results went back to normal. Agnico continued to monitor the quality of the effluent; 4 samples were collected during the month. The summary of the results is provided in Table 4 below.

Table 4: Effluent testing results at STP-FINAL (MEL-7) sampling station, September 2019

MEL-7	MEL-7 EFFLUENT QUALITY LIMITS	Sample Date	9/9/2019	9/16/2019	9/23/2019	9/30/2019
Parameter		Unit				
Biochemical Oxygen	80	mg/L	3	5	4	< 2
Demand, 5 Day						
Oil & Grease	5	mg/L	1.7	0.6	< 0.50	1.1
рН	6.0 - 9.5	pH units	6.97	6.74	6.79	6.33
Total Suspended Solids	100	mg/L	4	5	9	4
Atypical colonies		CFU/100mL	36	18500	106	30
Fecal Coliform	1000	CFU/100mL	< 2	< 2	< 2	< 2

Aerobic heterotrophic bacteria	CFU/100mL	72000	> 300 000	2400	2364
Total Coliform	CFU/100mL	< 2	< 100	< 2	< 2
Ammonia Nitrogen	mg/L	15	23	0.87	8.7
Nitrogen, Kjeldahl	mg/L	17	24	2	11
Nitrogen, Nitrate-Nitrite	mg/L	38.9	51.2	19.9	34
Phosphorus	mg/L	8.6	13	6.2	8.7

8. The Licensee shall, prior to the release of effluent from the Bermed Fuel Containment Facilities at Monitoring Program Station MEL-5 and the Landfarm Treatment Facility at Monitoring Program Station MEL-6 for the purpose of demonstrating compliance, sample for the parameters listed under Part D item 15.

In September, no water was discharged from the Fuel Containment Facilities (Monitoring station MEL-5) or the Landfarm Treatment Facility (Monitoring Station MEL-6).

9. The Licensee shall obtain representative samples of the water column below any ice where required under part F, Items 5 and 6. Monitoring shall include but not limited to the following:

**Total Suspended Solids** 

рΗ

Electrical Conductivity, and

Total trace Metals as determined by a standard ICP Scan (to include at a minimum, the following elements: Al, Sb, Ba, Be, Cd, Cr, Co, Cu, Fe, Pb, Li, Mn, Mo, Ni, Se, Sn, Sr, Tl, Ti, U, V, Zn), and Trace Arsenic and Mercury.

On-ice drilling was conducted in March and April 2019; samples are collected before, during and after drilling and sent for analysis. The complete set of analyses results was submitted with the May report.

10. Modify the monthly monitoring reports, starting April 2016, to include, at a minimum, waste water treatment options; and modifications of the freshet action plan.

From Nov, 2017 to April 2019, all treated sewage from the Exploration Camp STP was trucked and deposited in CP1. From April 15th 2019 to June, due to inconsistency in the amount of people at the exploration camp resulting in unsteady STP effluent results, AEM decided to transfer all treated water from the exploration STP to the main camp STP for a second treatment before being discharge in CP-1. Since early June, the treated sewage from the exploration camp is deposited in CP-1 as sampling results went back to normal.