

Figure 6. Temperature and dissolved oxygen depth profiles for the southeast basin of Sheardown Lake, May 2007.




Figure 7. Water quality sampling sites: May 2007.




Figure 8. Water quality sampling sites: August 2007.




Figure 9. Bathymetric map of the northwest basin of Sheardown Lake.

