



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 10-01-2018		REPORT TIME 9:45		<input type="checkbox"/> ORIGINAL SPILL REPORT, OR <input checked="" type="checkbox"/> UPDATE # 1 TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	B	OCCURRENCE DATE: MONTH – DAY – YEAR 09-30-2018		OCCURRENCE TIME 11:00		
C		LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE) NWB-2BC-WTP-1819		
	D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK/WTP MINE SITE			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E		LATITUDE DEGREES 65 MINUTES 02 SECONDS 14			LONGITUDE DEGREES 96 MINUTES 03 SECONDS 58	
	F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0		
G		ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION		
	H	PRODUCT SPILLED DIESEL		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 100 LITERS	U.N. NUMBER 1202	
I		SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
	J	SPILL SOURCE TRACTOR FUEL TANKS		SPILL CAUSE BROKEN CAP		AREA OF CONTAMINATION IN SQUARE METRES 15 M3
K		FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT
	L	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS				
M		<p>A tractor-trailer traveling north bound with two sea-cans, from Baker Lake to Whale Tail site, containing dry goods rolled-off the WTP road at km 51. Investigation on the cause of the incident is ongoing. On location, diesel fuel was found to be leaking from the cap of the tractor diesel tanks. The Environmental Department collected and contained the fuel on location. The tractor-trailer recovery work is ongoing and final determination of quantities will be specified within a follow-up report.</p> <p>There were no off site impacts or discharge to any receiving watercourses. Distance to the closest lake is estimated at 230 meters.</p> <p>Spill location : Northing: 65'19'46" Easting: 96'30'37" on Crown Land.</p> <p>Contact information : Robin Allard 819-759-3555 ext. 6744</p>				
	N	REPORTED TO SPILL LINE BY ROBIN ALLARD	POSITION SR COORDINATOR	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8197593555
ANY ALTERNATE CONTACT Nancy D-Harvey		POSITION SUPERINTENDENT	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT MEADOWBANK	ALTERNATE TELEPHONE 8677934610	
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
	LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC		SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						