



September 30, 2018 WTP Road

GN reference # : 2018-407

Please find the following information as a follow up to the Spill report submitted September 30th, 2018 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2BC-WTP1819, Part G, Item 5c.

Spill Description

A tractor-trailer traveling north bound from Baker Lake to Whale Tail site went off the WTP road at km 51. The tractor was tipped on its side and diesel fuel was slowly leaking from the cap on the fuel tank.

Spill location: Easting 65'19'46" 96'30'37"

There were no off site impact or discharge to any receiving watercourses. The distance to the closest lake is estimated at 230 meters.



Cause of Spill

The tractor-trailer was tipped on its side and diesel fuel was slowly leaking from the cap on the fuel tank.

Remediation Actions

Absorbent pads were laid out to contain the spill on the ground as well as a containment drum. Once the truck was placed back on the road and moved out of the area, the ground was scrapped clean and contaminated material was brought to the Meadowbank Landfarm area.



Corrective measures

Investigation on the cause of the incident is ongoing.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on September 30th, 2018 and the cleanup activities. Please contact the undersigned should you have any questions.



Tom Thomson | Environmental Coordinator

tom.thomson@agnicoeagle.com | Direct 819.759.3555 x6744

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunawut, Canada
XOC 0A0

agnicoeagle.com    