

NWB Annual Report

Year being reported: 2018

License No: Issued Date:
 Expiry Date:

Project Name:

Licensee:

Mailing Address:

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B Item 2

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	<input type="text" value="N/A"/>		
Water Quantity:	<input type="text" value="2"/>	Quantity Allowable Domestic (cu.m)	
	<input type="text" value="0"/>	Actual Quantity Used Domestic (cu.m)	
	<input type="text" value="40"/>	Quantity Allowable Drilling (cu.m)	
	<input type="text" value="0"/>	Total Quantity Used Drilling (cu.m)	

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No spills occurred in 2018.

Revisions to the Spill Contingency Plan

Other: (see additional details) ▼

Additional Details:

Updated Spill Contingency Plan required to include barge site.

Revisions to the Abandonment and Restoration Plan

Other: (see additional details) ▼

Additional Details:

Updated Abandonment and Restoration Plan required to include barge site.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

N/A

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A) ▼

Additional Details:

No water was used in 2018.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Additional Details:

No waste was deposited in 2018.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

N/A

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

N/A

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

N/A

Any additional comments or information for the Board to consider

Updated Spill Contingency Plan and Abandonment and Restoration Plan will be submitted prior to use of the barge landing site.

Date Submitted:

March 16, 2021

Submitted/Prepared by:

Tara Gunson APEX Geoscience Ltd.

Contact Information:

Tel: (780) 467-3532

Fax:

email: tgunson@apexgeoscience.com