

NWB Annual Report

Year being reported: 2023

License No: 2BE-ABP2328 Issued Date: April 3, 2023
 Expiry Date: April 2, 2028

Project Name: Arcadia Bay

Licensee: West Kitikmeot Resources Corp

Mailing Address: P.O. Box 6, 30B Mitik Street
 Cambridge Bay, NU XOB OCO

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

APEX Geoscience Ltd., on behalf of West Kitikmeot Resources Corp. West Kitikmeot Gold Corp. changed their name to West Kitikmeot Resources Corp. on November 24, 2023. See attached documents "231124 - Certificate and Articles of Amendment - Filed" and "240226 - Certificate of Amendment of Registration (Nunavut)."

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	N/A	
Water Quantity:	10	Quantity Allowable Domestic (cu.m)
	0	Actual Quantity Used Domestic (cu.m)
	289	Quantity Allowable Drilling (cu.m)
	0	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

No waste was produced in 2023.

A list of unauthorized discharges and a summary of follow-up actions taken.Spill No.: (as reported to the Spill Hot-line)Date of Spill: Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No spills occurred in 2023.

Revisions to the Spill Contingency PlanOther: (see additional details)

Additional Details:

Revisions to the Abandonment and Restoration PlanOther: (see additional details)

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

N/A

Results of the Monitoring Program including:**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**Not Applicable (N/A)

Additional Details:

No water was used in 2023.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;Not Applicable (N/A)

Additional Details:

No waste was deposited in 2023.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

N/A

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

N/A

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

No inspections were completed in 2023.

Any additional comments or information for the Board to consider

Date Submitted:
Submitted/Prepared by:
Contact Information:

February 15, 2024

Tara Gunson APEX Geoscience Ltd.

Tel: (780) 467-3532

Fax:

email: tgunson@apexgeoscience.com