

NWB Annual Report

Year being reported: 2008 ▼

License No: 2BE-ASH0611 **Issued Date:** June 1, 2006
Expiry Date: May 31, 2011

Project Name: Coronation Project

Licensee: Vaaldiam Resources. Ltd.

Mailing Address:
 55 University Ave.
 11th Floor, Suite 1105
 Toronto, ON M5J 2H7

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Stornoway Diamond Corporation
 (Vaaldiam Resources Ltd. has provided the NWB with written authorization for Stornoway Diamond Corporation to act on their behalf).

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Select ▼ Select ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	No water was used during 2008	
Water Quantity:	100 cu.m/day	Quantity Allowable Domestic (cu.m)
	0 cu.m/day	Actual Quantity Used Domestic (cu.m)
	n/a	Quantity Allowable Drilling (cu.m)
	n/a	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
- ☒ Sewage
- ☐ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

No water was used under the authority of this licence in 2008. Final abandonment and reclamation activities were conducted on the two camp locations, Phantom and RJ, in July of 2008 and a detailed final land use plan has been submitted to the NWB.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

Additional Details:

Revisions to the Abandonment and Restoration Plan

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

March 10, 2015

Submitted/Prepared by:

Stornoway Diamond Corporation

Contact Information:

Tel: 604-983-7750

Fax: 604-987-7107

email: Rhoppers@stornowaydiamonds.com