

Date: Aug 2, 2012

ENVIRONMENTAL INSPECTION REPORT

Page 2

Permit/License# NB007-C0014, 2BE-BAF-1116

- Site was inspected using helicopter chiverted out of Baginland's Mary River Project
- Garbage + debris everywhere at the main camp location ⁱⁿ
- Most weatherhousen structures have been removed, leaving contents exposed to weather
- Other than ^{large} refrigerator left in genshock, no other equipment such as ^{heating} stoves, ATV's or snowmachines were observed on site.
- Polar bear carcass left in middle of camp
- Heating fuel drums were noted in upright positions (at main camp)
- Sumps not backfilled; wastes left on site (in batteries, small containers of antifreeze etc.)
- Latrine shack left in place → previous latrine pits not remediated or recontoured ^{now}
- ~~the~~ ^{my} UV was in use for water treatment (did not look inside to confirm if bulb was back effective)
- * No secondary containment noted on site anywhere; lack of monitoring evident.
- o Wind blown debris along shore and in lake (mainly plastics observed). → ^{presence of liner} could not be confirmed
- o Plenty of debris + product stored in weatherhousen used as shop (between airstrip + main camp)
- * Overall condition of camp is feeble and constitutes a high risk to the receiving environment, especially where the fuel is concerned, as well as calcium chloride, left to weather unsecured and unmonitored. Proponent is to initiate clean-up of this camp
- ~~in the next 30 days~~ ^{my} within the next 30 days and provide notice to ANDC Field Operations (in the Inspector). Proponent is to provide record and photographs of site clean-up.
- * Some wastes on site will require special disposal (hazardous waste + biohazardous); proponent will be required to ^{now} provide copy of waste manifests confirming proper disposal.

Representative's Signature


RMO Initials

Inspector's Signature


MEUSN-JVY
N/A

Representative's Title

District Mgr. Initials