

NWB Annual Report

Year being reported: 2009

License No:

2BE-BAF0611

Issued Date:

July 10, 2006

Expiry Date:

July 31, 2011

Project Name:

Baffin Island Project

Licensee:

Pure Diamonds Exploration Inc.

Mailing Address:

Suite 800, 1199 West Hastings St., Vancouver, BC, V6E3T5

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):APEX Geoscience Ltd. (Geological Consultants). Completed the 2008 exploration program
on behalf of Pure Diamonds Exploration Inc.**General Background Information on the Project (*optional):**Surficial sampling
only during 2008**Licence Requirements: the licensee must provide the following information in accordance with****A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste**

Water Source(s):

Water for camp use only from local lake. Camp at N70 56 02.1 / W80 10 49.7

Water Quantity:

5 cu.m / day

Quantity Allowable Domestic (cu.m)

3cu.m/day

Actual Quantity Used Domestic (cu.m)

n/a

Quantity Allowable Drilling (cu.m)

n/a

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

Sewage and grey water holes were monitored to ensure sufficient capacity was not exceeded.

Non-combustible items were flown out.

Combustible waste was contained in a screened burning barrel and ashes were flown out.

Additional Details:

Water was pumped from lake into holding tank in the camp for daily camp use.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
Date of Spill:
Date of Notification to an Inspector:
Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

As per the Pure Diamond Spill Contingency Plan - Nunavut Operations

Revisions to the Spill Contingency Plan

Additional Details: None

Revisions to the Abandonment and Restoration Plan

Additional Details: None

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)
Removal of all camp and support material upon termination of the licence.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Water for camp use only from local lake. Camp at N70 56 06.4" / W80 10 56"

Additional Details: 35 Person camp at maximum capacity; only 9 person crew during 2008.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Pingujuak Camp: 17 W 529878 7870227 (NAD83), or N70 56 03.2 / W80 10 57"

Additional Details: Established camp

Results of any additional sampling and/or analysis that was requested by an Inspector

Additional Details: (date of request, analysis of results, data attached, etc)

n/a

No Drilling conducted during 2008

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

Additional Details: (Attached or provided below)

None

Any responses or follow-up actions on inspection/compliance reports

Additional Details: (Dates of Report, Follow-up by the Licensee)

None

Any additional comments or information for the Board to consider

license recently transferred
from Debeers Canada to
Pure Diamond. D.Besserer
managed last program on
behalf of Debeers and Pure
Diamond. No action items.

Date Submitted:
Submitted/Prepared by:
Contact Information:

Jan21/2009

Pure Diamonds Exploration Inc.; Eugene Beukman/ APEX Geoscience Ltd.; Dean Besserer,

Tel:	604-687-2038
------	--------------

Fax: 604-687-3141

email: ebeukman@pendergroup.ca

GPS Coordinates for water sources utilized

[illegible]

GPS Locations of areas of waste disposal

[illegible]