



Affairs Canada www.inac.gc.ca

Indian and Northern Affaires indiennes et du Nord Canada www.ainc.gc.ca

Kivalliq Region **PO Box 129** Rankin Inlet, NU XOC OGO

Your file - Votre référence

Our file - Notre référence

Majescor Resources Inc. Suite 103-5420, Canotex Road, Ottawa, Ont. K1J 1E9

Sept. 3, 2013

Re: Field Inspection - LUP N2008C0029 - Princess Mary Lake Area

On July 19, 2013, I conducted a field inspection at the above mentioned location.

A copy of the Inspection report is attached. After reading the report please sign and return a signed photocopy to my office. If you have any comments or suggestions, please feel free to attach them to the copy of this report. I apologize for the delay in forwarding this report to you.

Issues Identified during the inspection.

Campsite: No Campsite to inspect. - The site has been cleaned up.

Fuel Storage: NA

Water: NA

Waste: NA

Drilling Activities No drilling

Comments:



Printed on recycled paper - Imprimé sur papier recyclé

The site is coordinates 64' 05' 38.2"N 97'53.33"W on Princess Mary Lake area. The site is completely cleaned up and it recommended that this file be closed.

Please do not hesitate to contact me should you have any questions to comments

Yours truly,

₍₄) 4

Henry Kablalik, Resource Management Officer

Kivalliq Region Rankin Inlet, NU PO Box 129

XOC OGO

Tel: 867-645-2831 Fax: 867-645-02592

Henry.kablalik@inac.gc.ca

Date:	luly	19/	/ 13

ENVIRONMENTAL INSPECTION REPORT

Perm	ittee: (complete name and add	ress) Majescon	Reso	urces Inc.			
Suite 103-5420, Canotex Road Ottawa, Ont. KIJ-1E9							
	g² ∮			Permit Expiry Date	Last Previous Inspection		
Land	Use Permit No.	N20CBCOCA9		June 1 2010	Tel 19/10		
Quar	rying Permit No.	NAUCS COLOR	7	June 1, 2010	3009 1 / 10		
	· · · · · · · · · · · · · · · · · · ·						
0		0.4					
Contractor:				Subcontractor:			
	tion(a) Increated				<i>a</i> . 1		
LOCA	tion(s) Inspected:	un Camp	6405	138.2" N 97"53"	33"W		
Curre	ent Stage of Operation:	eaned UP					
		·					
Prog	ram Modifications Approved:						
					The state of the s		
	Condition	of Operation "A" - Accepta	able "U" - UI	nacceptable "N/A" - Not Applic	able		
	Operating Condition	n	Aspect In	spected			
			<u> </u>				
Α	Location as Permitted	4			A CONTRACTOR OF THE CONTRACTOR		
В	Timing as Permitted						
	Equipment as Approved						
D	Methods & Techniques						
E	Facilities						
F	Erosion	110					
G	Chemicals, Waste	NA					
	Wildlife & Fisheries Habitat	A A					
H		A A					
K	Ecological Resource	A	1				
	Fuel Storage						
L	Brush Disposal Matters Not Inconsistent	NA					
M		A					
N	Water Engineering	NA					
0	Water Supply	NA					
Р	Restoration Oversing Methods	A					
Q R	Quarrying Methods Sections 12 to 19 T.L.U.R.	NA					
	Sections 12 to 19 1.L.O.n.	A					
S							
Т							
Surveillance Network Program							
Expl	anatory Remarks (attach page 2	2, if required) This 5	ik ha	s been cleane	d + is		
no	w recommend	led for cle	arance				
				• • • • • • • • • • • • • • • • • • •			
		•		P	age 2 attached ☐ Yes ☐ No		
			N.				
Representative's Signature				Inspector's Signature			
i representative a digitation							
RMO Initials							
			. avi o midalo				
Representative's Title District Mgr. Initials					District Mgr. Initials		
rioprocentativo e rino							