NWB Annual Report	Year being reported: 2009 ▼
License No: 2BE-BOR0813	Issued Date: December 11, 2008
	Expiry Date: October 31, 2013
Project Name:	Borden Project
Licensee: Indic	cator Minerals Inc.
Mailing Address:	275 - 1075 West Georgia Street Vancouver BC V6E 3C9
	filing Annual Report (if different from Name of Licensee please clarify ne two entities, if applicable):
General Background Information	n on the Project (*optional):
No drilling explorat during 2009.	ion or camp activities were conducted on the Borden Property
Licence Requirements: the licer with	see must provide the following information in accodance
The state of the s	and waste disposal activities, including, but not limited to: methods of
waste management.	eywater management; drill waste management; solid and hazardous
Water Source(s):	
Water Quantity:	Quantity Allowable Domestic (cu.m)  Actual Quantity Used Domestic (cu.m)  Quantity Allowable Drilling (cu.m)  Total Quantity Used Drilling (cu.m)
Waste Management ☐ Solid Waste Dis	·
Sewage Drill Waste Greywater Hazardous Other: Additional Details:	

A list of unauthorized discharges and a summary of follow-up actions taken.

	Spill No.: n/a (as reported to the Spill Hot-line)
	Date of Spill: n/a Date of Notification to an Inspector: n/a
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)
	Please refer to the Indicator Minerals Inc. Spill Contingency Plan for the Barrow
	Project
Revisions	to the Spill Contingency Plan  N/A - not applicable  ▼
	Additional Details:
	none
Revisions	to the Abandonment and Restoration Plan
	N/A- not applicable ▼
	Additional Details:
	none
Progressi	ve Reclamation Work Undertaken  Additional Details (i.e., work completed and future works proposed)
	n/a
Results o	f the Monitoring Program including:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of
	each location where sources of water are utilized;
	Not Applicable (N'A)
	Additional Details:
	n/a
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of
	each location where wastes associated with the licence are deposited;
	Not Applicable (N/A)
	Additional Details:
	n/a

## Results of any additional sampling and/or analysis that was requested by an Inspector

	No additional sampling requested by an Inspector or the Board
	Additional Details: (date of request, analysis of results, data attached, etc)
	n/a
Any other de	etails on water use or waste disposal requested by the Board by November 1 of the year ed.
	No additional sampling requested by an Inspector or the Board
	Additional Details: (Attached or provided below)
	n/a
Any respons	es or follow-up actions on inspection/compliance reports
•	No inspection report issued by INAC   ▼
	Additional Details: (Dates of Report, Follow-up by the Licensee)
	n/a
Any addition	al comments or information for the Board to consider
any usuano	n/a
Date Submitt Submitted/Pi Contact Info	repared by: Andrea Maynes