Nunavut Water Board

Standard Form for Annual Reporting Requirements of NWB2 Exploration Water Licenses

Email:

NWB Annua	l Report	Year being reported: 2005 ▼
License No:	NWB2BRO0405	Issued Date: March 19, 2004
		Expiry Date: December 31, 2005
	Project Name:	Brodeur Property
	Licensee: Kenne	ecott Canada Exploration Inc
	Mailing Address:	#354-200 Granville St Vancouver, BC V6C 1S4
		filing Annual Report (if different from Name of Licensee please clarify e two entities, if applicable):
	Diamondex Resource	es Ltd., Operator
General Bac	kground Information	n on the Project (*optional):
	•	pied from 25 June to 3 August 2005 by a crew of between 3 and as used for showers, drinking, washing dishes and drilling.
Licence Req with	1 1	see must provide the following information in accodance
obtaining wa	nter; sewage and gre	and waste disposal activities, including, but not limited to: methods of eywater management; drill waste management; solid and hazardous
waste mana		
	Water Source(s): Water Quantity:	Domestic - unnamed lake adjacent to the camp, Drilling - 10 cu.m/day
	Waste Management Solid Waste Dis Sewage Drill Waste Greywater Hazardous Other: Additional Details: All solid waste and s	·

A list of unauthorized discharges and a summary of follow-up actions taken.

	Spill No.: No spills (as reported to the Spill Hot-line) Date of Spill: Not applicable Date of Notification to an Inspector: Not applicable
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc) There were no spills.
Revisions to	the Spill Contingency Plan
	Other: (see additional details)
	Additional Details:
	A Spill Contingency Plan was submitted in 2005 as part of the Water Licence Renewal Application.
Revisions to	the Abandonment and Restoration Plan
	Other: (see additional details)
	Additional Details:
	An Abandonment and Restoration Plan was submitted in 2005 as part of the Water Licence Renewal Application.
Progressive	Reclamation Work Undertaken
. regiocomo	Additional Details (i.e., work completed and future works proposed)
	To date there has been no reclamation work undertaken.
Results of th	ne Monitoring Program including:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized; Details described below
	Additional Details:
	Domestic - 73°14"49', -87°52"10' Drilling - Not applicable in 2005
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited; Details described below
	Additional Details:
	Camp - 73°14"49', -87°52"10' Drilling - Not applicable in 2005

Results of any additional sampling and/or analysis that was requested by an Inspector

	No additional sampling requested by an Inspector or the Board						
	Additional Details: (date of request, analysis of results, data attached, etc)						
Any other de	other details on water use or waste disposal requested by the Board by November 1 of the year greported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below)						
	No additional sampling requested by an Inspector or the Board						
	Additional Details: (Attached or provided below)						
Any respons	es or follow-up actions on inspection/compliance reports						
	No inspection and/or compliance report issued by INAC ▼						
	Additional Details: (Dates of Report, Follow-up by the Licensee)						
Any addition	al comments or information for the Board to consider						
,							
Date Submit Submitted/P Contact Info	repared by: Janet Stritychuk, Land Manager, Diamondex Resources						

GPS Coordinates for water sources utilized

	Latitude			Longitude			
Source Description	o Deg	, Min	, Sec	o Deg	, Min	, Sec	

GPS Locations of areas of waste disposal

Location Description (type)	Latitude			Longitude			
	o Deg	, Min	, Sec	o Deg	, Min	"Sec	