

NWB Annual Report

Year being reported: 2019

License No: **2BE-CBP1722** Issued Date: **September 19, 2017**
 Expiry Date: **September 18, 2022**

Project Name: **Committee Bay Project**Licensee: **5530 Nunavut Inc.**

Mailing Address: **Suite 1700, 666 Burrard Street
 Vancouver, BC V6C 2X8**

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

APEX Geoscience Ltd. (contractor assisting with permitting).

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B  Item 2 

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	N/A	
Water Quantity:	2	Quantity Allowable Domestic (cu.m)
	0	Actual Quantity Used Domestic (cu.m)
	40	Quantity Allowable Drilling (cu.m)
	0	Total Quantity Used Drilling (cu.m)


Waste Management and/or Disposal **N/A**

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:


Additional Details:

No field program was completed during 2019 at the Committee Bay Project.**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No spills took place during 2019 at the Committee Bay Project as no field program was conducted.**Revisions to the Spill Contingency Plan**SCP submitted and approved - no revision required or proposed 

Additional Details:

Revisions to the Abandonment and Restoration PlanAR plan submitted and approved - no revision required or proposed 

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No reclamation was required during 2019 at the Committee Bay Project as no field program was conducted.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized:

Not Applicable (N/A)

Additional Details:

No water was used during 2019 on the Committee Bay Project as no work was conducted.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited:

Not Applicable (N/A)

Additional Details:

No waste was produced during 2019 on the Committee Bay Project as no work was completed.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

March 20, 2019

Submitted/Prepared by:

Tara Gunson, APEX Geoscience Ltd. on behalf of 5530 Nunavut Inc., a wholly owned subsidiary of Western Atlas Resources Ltd.

Contact Information:

Tel: (780) 467-3532

Fax: (780) 467-4025

email: tgunson@apexgeoscience.com