

NWB Annual Report

Year being reported:

Select ▼

2016

License No: 2BE-CHI1218

Issued Date:

December 24, 2012

Expiry Date:

June 1, 2018

Project Name:

Chidliak

Licensee:

Peregrine Diamonds Ltd.

Mailing Address:

Suite 654 - 999 Canada Place
Vancouver, BC
V6C 3E1

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Peregrine Diamonds Ltd.

General Background Information on the Project (*optional):

Diamonds Project - Hall Peninsula of Baffin Island - Operations 2008 to present.
NTS 26B02, 26B03, 26B07 and 26B08

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 2



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Various

Water Quantity:

325m³

Quantity Allowable Domestic (cu.m)

11.62m³

Actual Quantity Used Domestic (cu.m)

2877m³

Quantity Allowable Drilling (cu.m)

0m³

Total Quantity Used Drilling (cu.m)

Authorized 25m³ per day domestic and 221m³ per day drill

Waste Management and/or Disposal

☒ Solid Waste Disposal

☒ Sewage

☐ Drill Waste

☒ Greywater

☐ Hazardous

☐ Other:

Additional Details:

Only greywater, sewage and solid waste generation during Summer 2016 program. Water was pumped from drainage next to camp.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

Additional Details:

Revisions to the Abandonment and Restoration Plan

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

Additional sampling requested by an Inspector or the Board (See below) ▼

Additional Details: (date of request, analysis of results, data attached, etc)

- 1) CH-6 Trench water monitoring - Report submitted separatley
- 2) CH-7 Cuttings area monitoring - Report submitted separately

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

No additional samping requested.

Any responses or follow-up actions on inspection/compliance reports

Select ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

None

Any additional comments or information for the Board to consider

None

Date Submitted:

October 17, 2016

Submitted/Prepared by:

David Willis

Contact Information:

Tel: 604-608-4524

Fax: 604-408-8881

email: dave@pdiam.com

GPS Coordinates for water sources utilized

[illegible]

GPS Locations of areas of waste disposal

Location Description (type) Datum: WGS84	Latitude			Longitude			
	° Deg	, Min	, Sec	° Deg	, Min	, Sec	
	Greywater (Approx.)	64	14	23	-66	20	43