

NWB Annual Report

Year being reported: 2008



Licence No: #2BE-CHI0813

Issued Date: 7 May 2008

Expiry Date: 1 June 2013

Project Name: Chidiak Project

Licensee: Peregrine Diamonds Ltd.

Mailing Address: 201 - 1250 Homer Street
Vancouver, BC V6B 1C6

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Exploration began in summer 2008, following granting of initial Prospecting Permits in 2007 and additional Prospecting Permits in 2008. Activities in 2008 consisted of establishment of a 15-person tent camp, airborne geophysics, ground-truthing of geophysical anomalies and collection of surficial sediment samples.

Licence Requirements: the licensee must provide the following information in accordance with

Part B



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	stream at 64° 14' 00" - 66° 21' 00"		
Water Quantity:	10.00 m ³ /day	Quantity Allowable Domestic (cu.m)	
	2.55 m ³ /day	Actual Quantity Used Domestic (cu.m)	
	50.00 m ³ /day	Quantity Allowable Drilling (cu.m)	
	N/A	Total Quantity Used Drilling (cu.m)	

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
☒ Sewage
☐ Drill Waste
☒ Greywater
☐ Hazardous
☐ Other:

Additional Details:

Sewage of avg.. 20.42 L/day total reported to outhouse at camp. Camp solid waste of avg. 205.58 L/day burnt in camp incinerator; rest flown out. Greywater resulting from water use of 2.55 m³/day reported to camp greywater sumps at 64 14' 24.6" - 66 20' 47.1" and 64 14' 25.1" - 66 20' 46.8".

A list of unauthorised discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

SCP was voluntarily updated and re-submitted to NWB, INAC , QIA and GN-DOE on 29 July 2008.

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

As an amendment to the water licence + land-use permit was sought in November 2008, a revised A&R Plan was submitted with the amendment project description.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No reclamation required in 2008. Use sites for collection of sediment samples were inspected prior to moving on to next site. Camp was cleaned up and secured prior to seasonal closure at end of Aug. 2008. Work is planned in 2009.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below



Additional Details:

Stream at 64° 14' 00" - 66° 21' 00" beside small tent-camp was utilised. Water use was limited and quantity is given above. Bottled water in recyclable jugs was flown in to supplement potable water for drinking.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below



Additional Details:

Sewage reported to the outhouse at camp (64° 14' 25.3" - 66° 20' 46.7") and combustible kitchen wastes were burnt in the camp incinerator, with the remaining waste flown out for landfill disposal.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

INAC officers inspected Chidliak camp, 14 August 2008; a report was submitted 17 September 2008. The undersigned spoke with an Inspector on 10 September, then corresponded on 16-17 December. Lands Inspector was generally happy with camp, but suggested secondary containment for drums + increase of sump capacity. Peregrine will address this in coming season.

Any additional comments or information for the Board to consider

Thank you for the opportunity to provide information relative to this small field programme conducted between the dates of 17 July and 28 August 2008. The programme population consisted of between 7 and 15 people for the duration, with the avg. camp population at 10. A sketch map of the camp is included, as well as photos showing camp layout.

Date Submitted:

19 December 2008

Submitted/Prepared by:

Shirley Standafer-Pfister on behalf of Peregrine Diamonds

Contact Information:**Tel:** 604-608-4524 (direct phone)**Fax:** 604-408-8881**email:** shirley@pdiam.com

]

GPS Co-ordinates for water sources utilised

[illegible]

GPS Locations of areas of waste disposal

[illegible]

0.2
2