



☒ Original  
☐ Follow-Up Report

LAND USE PERMIT INSPECTION FORM

Permittee	Representative
Tundra Copper Corporation	
Permit No. / Expiry	Representative's Title
LUP N2015C0009	
Other Authorizations	Land / Other Authorizations
Water Licence 2BE-COP1416	
Date of Inspection	Inspector
24 August 2017Baba Pedersen	
Activities Inspected	
<input checked="" type="checkbox"/> Camp <input checked="" type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input checked="" type="checkbox"/> Reclamation <input checked="" type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/hauling <input type="checkbox"/> :Other <input type="checkbox"/> Other:	

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable	
Section:				Term No.	Condition	Observation No.
31 (1)(a) Location and Area					A	1, 2 & 3
31 (1)(b) Time					A	All
31 (1)(c) Equipment						
31 (1)(d) Methods and Techniques					A	All
31 (1)(e) Type location, capacity and operation of facility					A	4 & 5
31 (1)(f) Control or prevent of flooding, erosion, and subsidence of Land						
31 (1)(g) Use, storage, handling and disposal of chemical or toxic materials					A	6
31 (1)(h) Wildlife and fisheries habitat						
31 (1)(i) Objects and places of recreation, scenic and ecological value						
31 (1)(k) Petroleum fuel storage					A	7
31 (1)(m) Matters not inconsistent with the regulations						

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Regulations	<input type="checkbox"/> Action Required
I Inspected 3 Sites associated with this Land Use Permit and Water Licence. First was the Drill Site located at N 67° 37' 18.5" W 115° 52' 53.5", second was the Hope Lake Airfield Staging Area located at N 67° 25' 47.6" W 116° 24' 31.5" and third was the Hope Lake Camp Area located at N 67° 26' 01.7" W 116° 25' 22.0".			
SECTION 2	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Regulations	<input type="checkbox"/> Action Required
As per the attached photos, the following is what I found at each location; 1. The Drill Site area was cleaned up nicely, 2. The Airfield Staging Area was cleaned up nicely, 3. The Camp & Fuel Cache Area had been reclaimed and cleaned up nicely, 4. The Camp Area had been reclaimed and cleaned up nicely, 5. The Core Boxes were stacked and stored in an orderly manner, 6. The Sumps had been reclaimed and cleaned up nicely, and 7. The Fuel Storage Area had been reclaimed and cleaned up nicely.			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Regulations	<input checked="" type="checkbox"/> Action Required
I Recommend Closure of both Land Use Permit N2015C0009 and Water Licence 2BE-COP1416.			
Licensee or Representative		Inspector's Name	
		Baba Pedersen	
Signature		Signature	
		Signed Original on File	
Date		Date	
		2017 November 21	

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

cc.        INAC, Manager Land Administration  
  
            Nunavut Water Board, Manager of Licencing





Date	Camera	Inspector	Authorization
2017 August 24		Baba Pedersen	N2015C0009 & 2BE-COP1416
Photo Log # DSC01039		Location (N 67° 37' 18.5" W 115° 52' 53.5")	
Photo 1			
Description: Drill Site			



Photo Log # DSC01047	Location (N 67° 25' 47.6" W 116° 24' 31.5")
Photo 2	
Description: Hope Lake Airfield Staging Area	







Photo Log # DSC01056

Location (N 67° 25' 46.5" W 116° 24' 38.2")

Photo 3

Description: Hope Lake Camp & Fuel Cache Area




Photo Log # DSC01092

Location (N 67° 26' 02.0" W 116° 25' 24.8")

Photo 4

Description: Reclaimed Hope Lake Camp Area







Photo Log # DSC01100

Location (N 67° 26' 02.6" W 116° 25' 24.2")

Photo 5

Description: Core Box Storage Area



Photo Log # DSC01106

Location (N 67° 26' 01.7" W 116° 25' 22.0")

Photo 6

Description: Reclaimed Sump Area







Photo Log # DSC01110

Location : Hope Lake Camp Fuel Storage Area

Photo 7

Description: Reclaimed Fuel Storage Area

