

## NWB Annual Report

Year being reported: Select ▼

2017

License No: 2BE-COP1721 Issued Date: June 19, 2017  
 Expiry Date: June 18, 2021

Project Name: Coppermine Project

Licensee: Tundra Copper Corp.

Mailing Address: Suite 654  
999 Canada Place  
Vancouver, BC  
V6K3E1

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Tundra Copper Corp.

## General Background Information on the Project (\*optional):

This report is being filed for the 2017 calendar year.

## Licence Requirements: the licensee must provide the following information in accordance with

Select ▼ Select ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of water; sewage and greywater management; drill waste management; solid and hazardous waste management

Water Source(s):	<span>Local</span>		
Water Quantity:	<span>5</span>	Quantity Allowable Domestic (cu.m)	
	<span>0</span>	Actual Quantity Used Domestic (cu.m)	
	<span>70</span>	Quantity Allowable Drilling (cu.m)	
	<span>0</span>	Total Quantity Used Drilling (cu.m)	

## Waste Management and/or Disposal

- ☐ Solid Waste Disposal  
☐ Sewage  
☐ Drill Waste  
☐ Greywater  
☐ Hazardous  
☐ Other:

Additional Details:

No waste generated in 2017

#### A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No spills in 2017

#### Revisions to the Spill Contingency Plan

▼

Additional Details:

No revisions

#### Revisions to the Abandonment and Restoration Plan

▼

Additional Details:

No Revisions

#### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Hope Lake Camp demobilized.

#### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each where sources of water are utilized;**

▼

Additional Details:

No water used in 2017.

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each where wastes associated with the licence are deposited;**

▼

Additional Details:

No wastes generated.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

No additional sampling.

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

No additional sampling

Any responses or follow-up actions on inspection/compliance reports

Inspection and Compliance Report received by the Licensee (Date):

Additional Details: (Dates of Report, Follow-up by the Licensee)

Inspection report was that demobilized camp was satisfactory. Inspection was conducted on August 24, 2017.

Any additional comments or information for the Board to consider

Date Submitted:

Feb. 9, 2018

Submitted/Prepared by:

David Willis

Contact Information:

Tel: (604) 608-4524

Fax:

email: dave@kaizendiscovery.com