

NWB Annual Report

Year being reported:

Select ▼

2021

License No: 2BE-COP1721

Issued Date: June 20, 2017

Expiry Date: June 20, 2021

Project Name: Coppermine Project

Licensee: Tundra Copper Corp.

Mailing Address:

Suite 654
999 Canada Place
Vancouver, BC
V6C3E1

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Tundra Copper Corp.

General Background Information on the Project (*optional):

This report is being filed for the 2021 calendar year.

Licence Requirements: the licensee must provide the following information in accordance with

Select ▼

Select ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Local	
Water Quantity:	5	Quantity Allowable Domestic (cu.m)
	0	Actual Quantity Used Domestic (cu.m)
	65	Quantity Allowable Drilling (cu.m)
	0	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

No waste generated in 2021

A list of unauthorized discharges and a summary of follow-up actions taken.Spill No.: (as reported to the Spill Hot-line)Date of Spill: Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

Additional Details:

Revisions to the Abandonment and Restoration Plan

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Additional Details:

--

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board	▼
---	---

Additional Details: (date of request, analysis of results, data attached, etc)

No additional sampling.

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board	▼
---	---

Additional Details: (Attached or provided below)

No additional sampling

Any responses or follow-up actions on inspection/compliance reports

Inspection and Compliance Report received by the Licensee (Date):	▼
---	---

Additional Details: (Dates of Report, Follow-up by the Licensee)

Inspection report was that demobilized camp was satisfactory. Inspection was conducted on August 24, 2017.
--

Any additional comments or information for the Board to consider

--

Date Submitted:

January 6, 2022

Submitted/Prepared by:

Mark Gibson

Contact Information:

Tel:	(604) 648-3984
------	----------------

Fax:	
------	--

email:	mark@kaizendiscovery.com
--------	--------------------------