

## NWB Annual Report

Year being reported:

2009



License No: NWB 2BE-CRA0710

Issued Date:

February 23, 2007

Expiry Date:

September 31, 2010

Project Name:

Committee Bay

Licensee:

CBR Gold Corp

Mailing Address:

Suite 220, 9797-45th Ave  
Edmonton  
Alberta  
T6E 5V8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

## General Background Information on the Project (\*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Hayes River, local unnamed rivers and ponds

Water Quantity:

10 cu.m per day

Quantity Allowable Domestic (cu.m)

2-4 cu.m per day

Actual Quantity Used Domestic (cu.m)

70 cu.m per day

Quantity Allowable Drilling (cu.m)

30-60 cu.m per day

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal☒ Sewage☐ Drill Waste☒ Greywater☐ Hazardous☐ Other:

Additional Details:

All exploration activities were conducted out of the Hayes. CBR Gold Corp adhered to all regulations concerning water and environmental issues and ensured that contractors and sub-contractors were also in compliance.

## A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:

None

(as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

### Revisions to the Spill Contingency Plan

Other: (see additional details)



Additional Details:

Updated SCP already submitted and awaiting approval

### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Camps and fuel storage sites were kept clean and tidy. Since camps are in seasonal use, the camps were shut down appropriately for winter.

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details described below



Additional Details:

Hayes Camp  
UTM 564613 7394173  
DD 66o39'30" 91o33'11"  
Crater Camp

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details described below



Additional Details:

Hayes Camp  
UTM 564613 7394173  
DD 66o39'30" 91o33'11"

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

--

**Any responses or follow-up actions on inspection/compliance reports**



Additional Details: (Dates of Report, Follow-up by the Licensee)

--

**Any additional comments or information for the Board to consider**

--

Date Submitted:

November 10, 2009

Submitted/Prepared by:

Jo Price

Contact Information:

Tel: 780 437 6624

Fax: 780 439 7308

email: [jop@cbrgoldcorp.com](mailto:jop@cbrgoldcorp.com)