



WATER LICENCE INSPECTION FORM

☐ Original

☐ Follow-Up Report

Licensee		Licensee Representative	
True North Gems Inc.		N/A	
Licence No. / Expiry		Representative's Title	
2BE-CRO0813			
Land / Other Authorizations		Land / Other Authorizations	
Date of Inspection		Inspector	
July 9, 2018		Jonathan Mesher	
Activities Inspected			
<input checked="" type="checkbox"/> Camp	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other:	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage
<input type="checkbox"/> Other:		<input type="checkbox"/> Other:	

Conditions:	A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected
Water Use		Site Conditions		Haz/Mat Management	
	Condition	Comment		Condition	Comment
Intake/Screen	A		Water Management Structures	A	
Flow Measure. Device	A		Culverts / Bridges	A	
Source:	A		Drainage	A	
Water Use:	A		Erosion / Sediment	A	
Recirculation (y /n)	N		Mitigation Measures	A	
			Reclamation Activities	A	
			Materials Storage	A	
Waste Disposal		Signage		Administrative	
Waste Water	A			Records	A
Solid Waste	A			Reports	A
Hazardous Waste	A			Plans	A
				Notifications	A
		Monitoring		Other	
			Sample Collection / Analysis	NI	
*The number in the comments field will correspond with specific comments provided below.					
Samples taken by Inspector:					
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

+SECTION 1

☒ Comments (s.____)

☐ Non-Compliance with Act or Licence (s.____)

☐ Action Required (s.____)

A Water licence inspection was conducted by J.Mesher of CIRNAC to ensure compliance with the Water Licence 2BE-CRO0813. On July 9th, 2018 the inspection was conducted and there was no evidence of water usage or deposits of waste at the location: N63 03 30.0 W70 45 00.0.

The Inspector has corresponded with the Nunavut Water Board (NWB) regarding outstanding requirements prior to recommending closure of this licence and the NWB has informed the inspector that the licensee is required to submit annual reports for 2010 to 2013. The licensee has since submitted the annual reports to the NWB and there are currently no outstanding documents required to be submitted.

The licensee is not permitted to do future deposits of waste or uses of water. Therefore, related to this licence, no deposits or use should ever occur under this licence unless authorized. If the NWB and the licensee have no concerns the inspector requests the closure of this licence.

SECTION 2

☐ Comments

☐ Non-Compliance with Act or Licence

☐ Action Required

Click here to enter text.

SECTION 3

☐ Comments

☐ Non-Compliance with Act or Licence

☐ Action Required

Click here to enter text.

Licensee or Representative	Inspector's Name
True North Gems Inc.	Jonathan Mesher
Signature	Signature
Date	Date
	August 10, 2018

Office Use Only:

Follow-up report to be issued by Inspector

☐ Yes ☐ No



CC: Licensing Department, NWB
 Justin Hack, Manager of Field Operations, INAC