## **Nunavut Water Board**

Standard Form for Annual Reporting Requirements of NWB2 Exploration Water Licenses

Under the terms of your water licence issued by the Nunavut Water Board ("NWB") for the use of water and the disposal of waste into water associated with mineral exploration (NWB2 Licenses), Licensees are required to submit to the NWB an Annual Report no later than March 31st of the year following the calendar year being reported.

In order to aid the Licensee with the preparation of the Annual Report and facilitate its review by the NWB, Licensees are **required** to use the following form.

## Recommendation and Helpful tips for use:

Metric units shall be used to report any relevant data.

How to Add additional space within Text boxes - Right click mouse on the row number (directly to the left of your screen) which falls within the text box range and click insert. Do not drag or drop text box to modify size of the text box because formatting will not be maintained and data will be lost. If you have large amounts of data recommend adding additional worksheets. Go to the help menu for assistance.

**Electronic versions should be submitted in Adobe to ensure protection of your information.** If you do not have shortcut keys to save as a PDF. Go to print menu . Choose to print "Entire Worksheet" then select printer option Adobe PDF and you will be prompted to save the document as a PDF document. Reminder ensure you have saved your document in Excel so that future changes can be made.

**Modify the Header -** Select "View" then "Header" from the main menu. Select "Custom Header" and change to reflect the valid Water Licence No.

Textboxes denoted with \* are optional.

Annual Reports shall be submitted by either fax, mail or email in adobe acrobat or Excel format to:

Nunavut Water Board c/o Manager of Licensing P.O. Box 119 Gjoa Haven, NU X0B 1J0 Tel: 867-360-6338

Fax:867-360-6369

Email: <u>licensing@nunavutwaterboard.org</u>

NWB Annua	l Report	Year being reported: 2008 <u>▼</u>	
License No:	NWB2DBY0509	Issued Date: September 9, 2005 Expiry Date: November 30, 2009	
	Project Name:	Darby Project	
	Licensee: Indica	tor Minerals Inc.	
	Mailing Address:	Suite 275-1075 West Georgia Street Vancouver, BC Canada V6E 3C9	
		filing Annual Report (if different from Name of Licensee please clarify e two entities, if applicable):	]
General Bac	kground Information	n on the Project (*optional):	J
Licence Req with		see must provide the following information in accodance	
	nter; sewage and gre	and waste disposal activities, including, but not limited to: me eywater management; drill waste management; solid and haza	
	Water Source(s): Water Quantity:	Lakes and creeks  2 cu.m/day Quantity Allowable Domestic (cu.m)	
		31 cu.mActual Quantity Used Domestic (cu.m)30 cu.m/dayQuantity Allowable Drilling (cu.m)0 cu.mTotal Quantity Used Drilling (cu.m)	
	Waste Management  Solid Waste Dis Sewage Drill Waste Greywater Hazardous Other:		
	Additional Details:	wasto was incinorated an site with non humable wastes (is	
	metals) and hazardo off-site as backhauls	waste was incinerated on site, with non-burnable wastes (ie ous wastes contained and flown to the appropriate waste facilities on regular service flights, and grey water was contained in a ed distal to any water source.	

A list of una	uthorized disc <u>harges and a sum</u> mary of follow-up actions taken.
	Spill No.: (as reported to the Spill Hot-line)
	Date of Spill:
	Date of Notification to an Inspector:
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)
Revisions to	the Spill Contingency Plan
	N/A - not applicable   ▼
	Additional Details:
	Revisions to the plan were submitted with the previous Annual Report.
D	the Alexa Language on L.D. of continue Disc.
Revisions to	the Abandonment and Restoration Plan
	N/A - not applicable   ▼
	Additional Details:
	Revisions to the plan were submitted with the previous Annual Report.
Progressive	Reclamation Work Undertaken
i rogressive	Additional Details (i.e., work completed and future works proposed)
	Empty fuel barrels from fuel caches across the north-eastern portion of the property (used during the airborne survey) were retrieved and brought to the main camp. The property needs to be flown in order to assure all remaining fuel caches/barrels have been removed or returned to the main camp.
Results of the	ne Monitoring Program including:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;
	Details attached   The state of
	Additional Details:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;
	Details attached   The state of
	Additional Details:

R	Results of any additional sampling and/or analysis that was requested by an Inspect							
<u>N</u>	No additional sampling requested by an Inspector or the Board   ▼							
A	dditional De	tails: (da	te of request, analysis	of results, data attac	hed, etc)			
Any other detable being reported		r use or	waste disposal requ	ested by the Board	by November 1 o	f the year		
		mpling req	uested by an Inspector or t	he Board	•	▼		
A	dditional De	tails: (Att	ached or provided bel	ow)				
Any responses	s or follow-ı	up action	ns on inspection/con	npliance reports				
N	lo inspection ar	nd/or comp	liance report issued by INA	C	•	▼		
A	Additional Details: (Dates of Report, Follow-up by the Licensee)							
1	INAC inspected the camp site in August 2008, after the camp was closed and							
1	there were r	no compa	any representatives o	n site. No inspection	report has been			
1	received by the Licensee as of submission of this Annual Report. Items that							
	were of immediate concern were passed on verbally to the project Operator,							
	Teck Cominco Limited on 11 August 2008. This included the presence of food							
	and garbage items remaining in the kitchen tent and some bags of garbage							
	remaining by the incinerator. All food items and gargabe remaining in the							
	kitchen tent have subsequently been removed. Garbage by the incinerator							
_ (	consisted of non-burnable metals, and too have subsequently been removed							
Any additional	comments	or infor	mation for the Board	to consider				
_						_		
Date Submitte	d:	March 1	4. 2009					
Submitted/Prepared by:			Doulos/Karen-Jane W	eir				
Contact Information:			604-669-4149					
		Fax:	604-669-4724					

email: karen.weir@teck.com

## **GPS** Coordinates for water sources utilized

	L	Latitude			Longitude		
Source Description	° Deg	, Min	, Sec	o Deg	Min	, Sec	
Lake (Camp)	67	19	3.53	93	2	14.74	

## **GPS** Locations of areas of waste disposal

Location Description (type)	Latitude Lon			ngitud	gitude	
	° Deg	, Min	, Sec	° Deg	, Min	°, Sec
Camp Sump	67	19	0.74	93	1	57.01