

**NWB Annual Report**

**Year being reported:** 2010 ▼

**License No:** 2BE-DBY1014 **Issued Date:** January 7, 2010  
**Expiry Date:** December 31, 2014

**Project Name:** Darby Project

**Licensee:** Indicator Minerals Inc (now Bluestone Resources Inc.)

**Mailing Address:**  
 1020 - 800 West Pender Street  
 Vancouver BC  
 Canada  
 V6C 2V6

**Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):**

Teck Resources Limited (partners on the Darby Project)

**General Background Information on the Project (\*optional):**

**Licence Requirements: the licensee must provide the following information in accordance with**

Select ▼

Select ▼

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):	Lake at the camp.		
Water Quantity:	32 cu.m/day	Quantity Allowable Domestic (cu.m)	
	120 cu m	Actual Quantity Used Domestic (cu.m)	
		Quantity Allowable Drilling (cu.m)	
	0	Total Quantity Used Drilling (cu.m)	

**Waste Management and/or Disposal**

- ☐ Solid Waste Disposal
- ☒ Sewage
- ☐ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

**Additional Details:**

Sewage was incinerated prior to dismantling of the camp.

**A list of unauthorized discharges and a summary of follow-up actions taken.**

**Spill No.:** (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Not Applicable (N/A)



Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Not Applicable (N/A)



Additional Details:

All waste was incinerated in 2011.

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

A final site inspection is expected in 2012.

**Any additional comments or information for the Board to consider**

Accompanying this report are photographs of the previously existing Stellar Camp, and the current condition of the camp site after removal in 2011.

**Date Submitted:**

May 29, 2012

**Submitted/Prepared by:**

Indicator Minerals Inc/Karen-Jane Weir

**Contact Information:**

**Tel:** 604.699.4149

**Fax:** 604.699.4724

**email:** [karen.weir@teck.com](mailto:karen.weir@teck.com)

