

WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
Tri Origin Exploration	Off site- Meghan Hewton
Licence No. / Expiry	Representative's Title
2BE-EDE0608	P. Geo
Land / Other Authorizations	Land / Other Authorizations
N2005C0036	--
Date of Inspection	Inspector
07/06/15	WRO C. Wilson
Activities Inspected	
<div><div><input type="checkbox"/> Camp</div><div><input type="checkbox"/> Roads/Hauling</div></div> <div><div><input type="checkbox"/> Drilling</div><div><input type="checkbox"/> Other: Culvert</div></div> <div><div><input type="checkbox"/> Mining</div></div> <div><div><input type="checkbox"/> Construction</div><div><input type="checkbox"/> Other: Bridge</div></div> <div><div><input checked="" type="checkbox"/> Reclamation</div></div> <div><div><input type="checkbox"/> Fuel Storage</div></div>	

Conditions:

A - Acceptable

C - Concern

U - Unacceptable

NA – Not Applicable

NI – Not Inspected

Water Use	Condition	Comment	Site Conditions	Condition	Comment	Haz/Mat Management	Condition	Comment
Intake/Screen	NA		Water Management Structures	NA		Storage	NA	
Flow Measure. Device	NA		Culverts / Bridges	NA		Spills	NA	
Source:	NA		Drainage	NA		Spill Plan	NA	
Water Use:	NA		Erosion / Sediment	NA				
Recirculation (y /n)	NA		Mitigation Measures	NA		Administrative		
			Reclamation Activities	A		Records	NA	
			Materials Storage	NA		Reports	NA	
Waste Disposal			Signage	NA		Plans	A	
Waste Water	NA					Notifications	NA	
Solid Waste	A		Monitoring			Other		
Hazardous Waste	NA		Sample Collection / Analysis	NA				

*The number in the comments field will correspond with specific comments provided below.

Samples taken by Inspector:	Location(s):
<div><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</div>	

SECTION 1

☒ Comments (s.1)

☐ Non-Compliance with Act or Licence (s.__)

☐ Action Required (s.__)

Pre-inspection

N2005C0036 was issued to Tri-Origin Exploration (“Tri-Origin”) for the use of land at the Edehon Lake Project. A final inspection was attempted in 2013 but outstanding issues were noted. Tri-Origin submitted a remedial action plan to the inspector which detailed a commitment to remove all remaining materials located at an airfield near the Edehon Lake Project Area.

Observations

- Materials associated with the Edehon Lake Project appeared to have been removed.

- A small area of burnt ground noted though all the ash residues have been removed.

- The site has been restored to the satisfaction of the inspector.

Click here to enter text.

SECTION 3

☒ Comments (s.__)

☐ Non-Compliance with Act or Licence, (s.__)

☐ Action Required (s.__)

The airfield at Edehon Lake is a popular airstrip and fuel cache therefore let the record show that the location appeared vacant and restored to a natural state at the time of inspection. The inspector supports the closure of the Licence.

Licensee or Representative	Inspector's Name
	Christine Wilson
Signature	Signature
	Original Signed on file
Date	Date
	09/08/2015

Office Use Only: Follow-up report to be issued by Inspector

☐ Yes ☒ No