



October 17, 2012

Christine Wilson

Resource Management Officer, Field Operations Unit
Aboriginal Affairs
Nunavut Regional Office
P.O. Box 100
Iqaluit, Nunavut X0A 0H0

Licence: 2BE-GAR0710

Sent via Email: Christine.Wilson@aandc.gc.ca

RE: Compliance Plan for Water Licence 2B2-GAR0710; Garry Lake Project

On July 30, 2012 a compliance inspection was conducted by Aboriginal Affairs and Northern Development Canada (AANDC) at Uravan Minerals Inc (Uravan) camp located at coordinates N65° 34' 52" - W100° 00' 31", at the northern end of Lower Garry Lakes, Nunavut. For reference the Water Use Inspection Report is attached.

Pursuant to the inspection report, Uravan has prepared a Compliance Plan to remove all infrastructure and materials from the site as follows:

1. Between July 15th to August 15th 2013 Uravan and/or its expeditor will remove all infrastructure and site material, including all fuel caches (full or empty drums) from the site.
2. Based on the inspection report, the attached photos and to the best of our knowledge the site clean up will consist of removing 5 wood tent platforms, other miscellaneous small auxiliary wood structures, 5 drums of Jet A fuel, 6 drums of diesel fuel and 2 empty drums.
3. On or before August 31, 2013, Uravan will provide AANDC a completion of work summary that outlines the items removed and photographs of the site.
4. Because it is currently uncertain between July 15th and August 15th as to exactly when the site clean-up will commence Uravan will notify AANDC when the clean up operations have commenced and again when these operations are completed.

Should you have any further questions, please give me a call at your earliest convenience.

Best regards,

A handwritten signature in blue ink, appearing to read "Larry Lahusen", is written over a horizontal line.

Larry Lahusen, CEO
Uravan Minerals Inc.

CC: Robin Ikkutisluuk
Nunavut Water Board
Email: licensingadmin@nunavutwaterboard.org



WATER USE INSPECTION REPORT FORM

Date: July 30, 2012	Licensee Rep. Site is inactive
Licensee: Uravan Minerals Inc.	Licence No: 2BE-GAR0710

Comments: A compliance inspection was conducted on the 30th of July 2012 at the Garry Lake Project (N65° 34' 52" W100° 00' 31") owned by Uravan Minerals Inc.

WATER SUPPLY

Source(s): Unnamed Lake	Quantity used: Unknown
Owner:/Operator: Uravan Minerals Inc.	

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Intake Facilities: NA	Storage Structure: NA	Treatment System: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

Comments: No water was being used at the time of the inspection

WASTE DISPOSAL

Sewage: Sewage Treatment System: NA

Natural Water Body: NA	Continuous Discharge (land or water): NA	
Seasonal Discharge: NA	Wetlands Treatment: Unknown	Trench: None

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: NA
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: NA
Dams, Dykes: NA	Freeboard: NA	Spills: NA
Construction: NA	O&M Plan: NI	A&R Plan: NI
Periods of Discharge: NA	Effluent Discharge Rate: None	

Comments: The Inspector noted the following on site

- Five wooden tent pads
- Wood camp furniture

FUEL STORAGE:

Owner/Operator:

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: NA	Water within Berms: NA	Evidence of Leaks: NA
Drainage Pipes: NA	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: NA	

Comments: The inspector noted the following

- Empty drums located at the air strip
- Full drums outside secondary containment

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected	Owner /Operator: Inactive	
0	INAC: NA	
Signs Posted	SNP: none	Warning:
Records & Reporting: No annual report was submitted after 2007		
Geotechnical Inspection: N/A		

Non-Compliance of Act or Licence:



The water license has been expired since December 31, 2010 therefore the license is required to remove all remaining items.

Part I Item 7

*The Licensee shall remove from the site, **all infrastructure** and site materials, including but not limited to, **all fuel caches, drums, barrels**, buildings and contents, docks, water pumps and lines, material and equipment prior to the expiry of this Licence.*

The Licensee is reminded that all terms and conditions still apply after the expiry. The Licensee has 30 days to submit a detailed plan as to how and when this action will occur.

Christine Wilson
Inspector's Name

Sent by E-mail Original on File
Inspector's Signature

Representative Name

Representative's Signature

Andrew Keim- A/Manager Field Operations
Phyllis Beaulieu – Manager Licensing- Nunavut Water Board

Contact Information:
Christine Wilson
Resource Management Officer
Aboriginal Affairs and Northern Development Canada
Building 918 – Box 100
Iqaluit, Nunavut XOA OHO
867-975-4296 Ph
867-979-6445 Fx
Christine.Wilson@aandc.gc.ca



