

## NWB Annual Report

Year being reported: 2007 ▼

License No: 2BE-GAR0710 Issued Date: May 9, 2007  
 Expiry Date: December 31, 2010

Project Name: Garry Lake Project

Licensee: Uravan Minerals Inc.

Mailing Address: 204-2526 Battleford Ave. SW  
 Calgary AB  
 T3E 7J4

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

## General Background Information on the Project (\*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

|                  |              |                                      |  |
|------------------|--------------|--------------------------------------|--|
| Water Source(s): | Unnamed Lake |                                      |  |
| Water Quantity:  | <5.0/day     | Quantity Allowable Domestic (cu.m)   |  |
|                  | 1.2/day      | Actual Quantity Used Domestic (cu.m) |  |
|                  |              | Quantity Allowable Drilling (cu.m)   |  |
|                  | 0            | Total Quantity Used Drilling (cu.m)  |  |

## Waste Management and/or Disposal

- ☒ Solid Waste Disposal  
☐ Sewage  
☐ Drill Waste  
☒ Greywater  
☐ Hazardous  
☐ Other:

Additional Details:



**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details described below ▼

Additional Details:

65°33'29" N / 100°04'14" W, west shore of N-S oriented lake south of Garry Lake

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Not Applicable (N/A) ▼

Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

**Date Submitted:**

June 4, 2008

**Submitted/Prepared by:**

Ian Fraser, Senior Geologist

**Contact Information:**

**Tel:** (403) 264 2630

**Fax:** (403) 264 2629

**email:** [ifraser@uravanminerals.com](mailto:ifraser@uravanminerals.com)