

NWB Annual Report

Year being reported: 2014 ▼

License No: 2BE-GEO1015 **Issued Date:** June 9, 2010
Expiry Date: June 30, 2015

Project Name: GEORGE LAKE, BACK RIVER PROJECT

Licensee: SABINA GOLD AND SILVER CORP

Mailing Address:
 930 WEST 1ST STREET
 SUITE 202
 NORTH VANCOUVER, BC V7P 3N4

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

SABINA GOLD AND SILVER CORP

General Background Information on the Project (*optional):

There was no water withdrawal or waste disposal in 2014 at the George Lake Project.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	George lake for domestic, lakes proximal to drilling		
Water Quantity:	45	Quantity Allowable Domestic (cu.m)	
		Actual Quantity Used Domestic (cu.m)	
	130	Quantity Allowable Drilling (cu.m)	
		Total Quantity Used Drilling (cu.m)	

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
- ☒ Sewage
- ☒ Drill Waste
- ☒ Greywater
- ☒ Hazardous
- ☐ Other:

Additional Details:

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

N/A

Revisions to the Spill Contingency Plan

N/A - not applicable



Additional Details:

Revisions to the Abandonment and Restoration Plan

N/A - not applicable



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

N/A

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A)



Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)



Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

A Plan was to be submitted to the Inspector as to how core will be moved 31 meters away from George Lake. Plan was submitted on December 5, 2014 and accepted by the Inspector on December 9, 2014.

Any additional comments or information for the Board to consider

Date Submitted:

April 8, 2014

Submitted/Prepared by:

John Laitin

Contact Information:

Tel:

Fax:

email: jlaitin@sabinagoldsilver.com