

## NWB Annual Report

Year being reported: 2005 ▼

License No: NWB2GEO0210

Issued Date: July 3, 2002

Expiry Date: December 31, 2010

Project Name: George Lake

Licensee: Kinross Gold Corporation

Mailing Address: 802 E. Winchester, Suite 100  
Murray, Utah 84107  
USA

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Dundee Precious Metals (operator of George Lake property)

## General Background Information on the Project (\*optional):

Mineral Exploration program

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 1 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Occurance Lake, Lyttle Lake

Water Quantity:

100

Quantity Allowable Domestic (cu.m)

0

Actual Quantity Used Domestic (cu.m)

100

Quantity Allowable Drilling (cu.m)

800.8


Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal☒ Sewage☒ Drill Waste☐ Greywater☐ Hazardous☐ Other:

Additional Details:

The volume 100m cu. is a combined volume between domestic and drilling.



A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

### Revisions to the Spill Contingency Plan

Select



Additional Details:

An updated Spill Contingency Plan has been forwarded to your office earlier this month.

### Revisions to the Abandonment and Restoration Plan

Select



Additional Details:

An updated Abandonment and Restoration Plan has been forwarded to your office earlier this month.

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Drill sites are regularly reclaimed after activity has occurred.

### Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A)



Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)



Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**Select 

Additional Details: (date of request, analysis of results, data attached, etc)

N/A

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**Select 

Additional Details: (Attached or provided below)

N/A

**Any responses or follow-up actions on inspection/compliance reports**Select 

Additional Details: (Dates of Report, Follow-up by the Licensee)

N/A

**Any additional comments or information for the Board to consider**

Date Submitted:  
Submitted/Prepared by:  
Contact Information:

March 21, 2006

John Laitin

Tel: 604 484-4224

Fax: 604 484-4587

email: [jlaitin@dundeeprecious.com](mailto:jlaitin@dundeeprecious.com)