

NWB Annual Report

Year being reported: Select ▼

License No: 2BE-GEO1520 **Issued Date:** May 30, 2015
Expiry Date: May 29, 2020

Project Name: GEORGE LAKE, BACK RIVER PROJECT

Licensee: SABINA GOLD AND SILVER CORP

Mailing Address: Suite 375, Two Bentall Centre,
555 Burrard St., Box 220
Vancouver, BC. V7X 1M7

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

SABINA GOLD AND SILVER CORP

General Background Information on the Project (*optional):

George River Water Licence which includes the Marine Laydown Area at Bathurst Inlet.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	N/A		
Water Quantity:	45	Quantity Allowable Domestic (cu.m)	
		Actual Quantity Used Domestic (cu.m)	
	130	Quantity Allowable Drilling (cu.m)	
		Total Quantity Used Drilling (cu.m)	

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

No water use or waste disposal occurred. All personnel were based out of Goose Lake Camp and any water consumed was from Goose Lake. All waste was returned to Goose Lake Camp. Attached is Figure 1.0 that illustrates drill holes at the Marine Laydown Area.

A list of unauthorized discharges and a summary of follow-up actions taken.Spill No.: (as reported to the Spill Hot-line)Date of Spill: Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No Spills occurred within the boundaries of the George Lake Water Licence.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Soil sampling drilling occurred and no water was utilized nor wastes produced.

Results of the Monitoring Program including:**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Not Applicable (N/A)



Additional Details:

No monitoring as per conditions of the water licence occurred.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)



Additional Details:

No wastes were produced. All personnel were based at Goose Lake.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

March 31, 2016

Submitted/Prepared by:

John Laitin

Contact Information:

Tel:

Fax:

email: jlaitin@sabinagoldsilver.com

