



Land Use Permit Inspection Report

Original
 Follow-Up Report

Authorization	Representative
B2Gold Corporation	Dan Gagnon
Authorization No. / Expiry	Representative's Title
2BE-GOO2028/February 18, 2028	General Manager
Inspection Date	Inspector
March 03, 2026	Isaiah James Bolt
Other Authorization/s	
2AM-BRP18 ,N2024F0027,076J712-7-2, 2BE-GEO2025,2BE-GOO2028,2BE-MLL2328, 076G/9-1-2	
Activities Inspected	
<input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Camp, Commercial <input type="checkbox"/> Drilling <input checked="" type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input checked="" type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input checked="" type="checkbox"/> Winter Hauling <input type="checkbox"/> Camp, Private <input type="checkbox"/> Other <small>Click or tap here to enter text.</small>	

Section 1 Comments

On March 03, 2026 Resource Management Officer Isaiah James Bolt (Inspector) for Crown Indigenous Relations and Northern Affairs Canada (CIRNAC), conducted an inspection of 2BE-GOO2028 (License) issued to B2Gold (Proponent) to ensure compliance against their license.

Accompanying the Inspector was Chris LeGoffe Environmental Superintendent of B2Gold and Kyle Amsel, Inspector for CIRNAC.

Inspection of Exploration camp began at 12:20pm on March 03, 2026.

- At the Major drilling laydown, Inspectors observed pales outside of containment as well as a drum out of containment (Photo #1). Inside the drum were used oil filters, the drum was not covered and was exposed to the elements.
- Photo #2 shows 2 jerry cans outside of containment at major drilling laydown.
- Inspectors observed a wooden box used as secondary containment and a fuel drum stand, the box was full of snow (Photo #3)
- The south side grey water discharge location for 2BE-GOO2028 (Exploration camp) was observed to be backed up with ice. Grey water was observed flowing out of the line upstream of the discharge location. (Photo #4 and #5). No signage was posted at this discharge location.
- The truck refuelling station at exploration camp was inspected (Photo #6). Snow saturated with fuel was observed along the base and up the wall of the fuel transfer box.
- The North grey water discharge for 2BE-GOO2028 location was inspected (Photo #7). Signage was posted at this location.
- Exploration camp's water log is provided on (Photo #8). The photo also shows the number of people in camp at the time of inspection.

Section 2 Non-Compliance

- Used oil filters in an open container(drum) exposed to the elements as well as Pales, Jerry cans and drums outside of containment.
- "Secondary containment" filled with snow. (wooden box)

Part H item #2 of the issued water license states: "The Licensee shall prevent any chemicals, petroleum products or Wastes associated with the project from entering Water."

Section 3 Action Required

Ensure all Hazardous materials/waste containers are placed in secondary containment.

Ensure snow built up in the fuel stands that are used as "Secondary containments" is removed and treated as contaminated snow.

Please have Actions Required completed by May 15, 2026 and send completed actions to me at James.bolt@rcaanc-cirnac.gc.ca



Licensee or Representative <i>David Gagnon</i>	Inspector's Name Isaiah James Bolt
Signature <i>David Gagnon</i>	Signature <i>James Bolt</i>
Date 17/04/2026	Date 17/04/2026

Office Use Only: Follow-up report to be issued by Inspector Yes No

PHOTO LOG

Date: March 03, 2026	Authorization Number: 2BE-GOO2028	Camera/Model: Olympus TG-6	Inspector Isaiah James Bolt
Photo # 1	Coordinates:		



Description:
 Buckets seen on the stairs outside of containment. An open drum on the pallet is filled with used oil filters, no covering, exposed to the elements, snow accumulating inside.



Photo # 2

Coordinates:



Description:

Jerry cans outside of containment.

Photo # 3

Coordinates:



Description:

Heating fuel stand filled with snow.



Description:
 South side grey water discharge location at exploration camp. No signage.



Description:
 South side grey water discharge location, the person at the back is seeing where grey water is flowing out from.



Photo # 6

Coordinates:



Description:

Snow saturated with fuel seen at the base of the refuelling station.

Photo # 7

Coordinates:



Description:

Fuel drum out of containment at the truck refill station at exploration camp.



Photo # 8 Coordinates:



Description:
North side exploration camp grey water discharge Location.

Photo # 9 Coordinates:

Date	Name	Comment	Main Dry Meter Reading m ³			Monthly Exploration Camp Water Usage	Site Population	Chlorine Content
			From	To	Usage (m ³)	Usage (m ³)	# Persons	
01-Mar-26	Johnny.L		20196.2	20201.3	5.1	177.5	74	0.28
02-Mar-26	Johnny.L		20201.3	20206.7	5.4		76	0.3
03-Mar-26	Mike .E		20206.7	20212.3	5.6		74	0.32
04-Mar-26	Mike .E		20212.3	20218.5	6.2		74	0.35
05-Mar-26	Mike .E		20218.5	20224.0	5.5		73	0.33
06-Mar-26	Mike .E		20224.0	20230.4	6.4		73	0.36
07-Mar-26	Mike .E		20230.4	20236.1	5.7		73	0.37
08-Mar-26	Mike .E		20236.1	20242.0	5.9		73	0.32
09-Mar-26	Mike .E		20242.0	20248.6	6.6		75	0.3
10-Mar-26	Mike .E		20248.6	20254.3	5.7		75	0.29
11-Mar-26	Mike .E		20254.3	20260.1	5.8		74	0.32
12-Mar-26	Mike .E		20260.1	20266.4	6.3		72	0.33
13-Mar-26	Mike .E		20266.4	20272.2	5.8		72	0.37
14-Mar-26	Mike .E		20272.2	20278.5	6.3		71	0.34
15-Mar-26	Mike .E		20278.5	20285.0	6.5		71	0.39
16-Mar-26	Mike .E		20285.0	20294.1	9.1		71	0.31
17-Mar-26	Mike .E		20294.1	20299.2	5.1		75	0.32
18-Mar-26	Mike .E		20299.2	20304.4	5.2		75	0.33
19-Mar-26	Mike .E		20304.4	20309.7	5.3		75	0.34
20-Mar-26	Mike .E		20309.7	20314.8	5.1		74	0.34
21-Mar-26	Mike .E		20314.8	20320.0	5.2		74	0.32
22-Mar-26	Mike .E		20320.0	20325.3	5.3		74	0.38
23-Mar-26	Mike .E		20325.3	20330.5	5.2		76	0.37
24-Mar-26	Mike .E		20330.5	20335.8	5.3		76	0.35
25-Mar-26	Mike .E		20335.8	20341.0	5.2		78	0.39
26-Mar-26	Mike .E		20341.0	20346.1	5.1		78	0.41
27-Mar-26	Mike .E		20346.1	20351.4	5.3		71	0.45
28-Mar-26	Mike .E		20351.4	20356.5	5.1		71	0.32
29-Mar-26	Mike .E		20356.5	20361.8	5.3		71	0.33
30-Mar-26	Mike .E		20361.8	20368.2	6.4		71	0.31
31-Mar-26	Mike .E		20368.2	20373.7	5.5		72	0.34

Description:
Exploration camp water logs as well as the camp population at the time of inspection.