

NWB Annual Report

Year being reported: 2005 ▼

License No: NWB2GOO0510 Issued Date: March 11, 2005
 Expiry Date: March 31, 2010

Project Name: Goose Lake

Licensee: Was Miramar Mining, now is Dundee Precious Metals

Mailing Address: 3220-666 Burrard St
 Vancouver, BC.
 V6C 2X8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Dundee Precious Metals

General Background Information on the Project (*optional):

Exploration Camp with exploration drilling

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.


Water Source(s):	Goose Lake	
Water Quantity:	100 cu. m/day	Quantity Allowable Domestic (cu.m)
	1509	Actual Quantity Used Domestic (cu.m)
	100 cu. m/day	Quantity Allowable Drilling (cu.m)
	2802.8	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
☒ Sewage
☒ Drill Waste
☒ Greywater
☒ Hazardous
☐ Other:

Additional Details:

The 100 m. cu mentioned above (domestic and drilling) is a combined allowable quantity, not 100m. cu for each application.



A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No spills occurred in 2005

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below ▼

Additional Details:

65 32' 43.54" N / 106 25' 34.64" W

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below ▼

Additional Details:

65 32' 31.36" N / 106 25' 35.03" W

Results of any additional sampling and/or analysis that was requested by an Inspector

Select ▼

Additional Details: (date of request, analysis of results, data attached, etc)

N/A

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

Select ▼

Additional Details: (Attached or provided below)

N/A

Any responses or follow-up actions on inspection/compliance reports

Select ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

N/A

Any additional comments or information for the Board to consider

N/A

Date Submitted:

March 21, 2006

Submitted/Prepared by:

John Laitin

Contact Information:

Tel: 604 985-2572

Fax: 604 980-0731

email: jlaitin@dundeeprecious.com